

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35390

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0512/2020/TF
Date	:	20-Apr-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Koh Wai Lan Audrey
Address	:	3 Amber Gardens #17-13 Singapore 439972
Telephone	:	(HP) +65 98322378
Type of Claim	:	Own Damage Claims
Policy No.	:	1900089792
Vehicle No	:	SKE 290 Y
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	23/4/2019
Engine No	:	CVK 077611
Chassis No	:	WAUZZZF55KA035017
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	21-Jul-20
Place of Accident	:	Shaw Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKW 290 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00 ✓	✓
2	To dismantle and renew rear bumper. To repair rhs rear fender. Re-organise crash management components. Reinstall all parts removed.		\$ 1,600.00 500 ✓	✓
3	To respray rear bumper and rhs rear fender.		\$ 2,000.00 880 1100 ✓	✓
4	To renew rhs rear exhaust silencer and align to position.	S/N	\$ 480.00 x	
5	To carry out diagnostic check.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u>\$ 4,632.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKW 290 Y

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER <i>Defend</i>	\$	2,504.00	✓ 2003-20
2	REAR BUMPER FIXING PARTS <i>2 piece new</i>	\$	163.00	+
3	REAR BUMPER SECURING STRIP <i>2 piece new</i>	\$	176 220.00	✓ S.S.
4	REAR BUMPER CHROME TRIM <i>cracked</i>	\$	804 1,005.00	✓
5	REAR BUMPER REFLECTOR - RH <i>cracked</i>	\$	32.24 41.00	✓
6	REAR OUTER TAIL LIGHT - RH <i>cracked</i>	\$	903.21 1,129.00	✓
7	REAR OUTER TAIL LIGHT TRIM - RH <i>new</i>	\$	30.00	+
8	REAR INNER TAIL LIGHT - RH	\$	1,008.00	+
9	REAR INNER TAIL LIGHT TRIM - RH <i>2 piece new</i>	\$	30.00	+
10	REAR BUMPER CARRIER <i>2 piece new</i>	\$	886.00	+
11	REAR BUMPER CARRIER SEAL	2 \$	28.00	+
12	REAR BUMPER TOP GUIDE SECTION - LH / RH	\$	44.00	? X new
13	REAR BUMPER TOP GUIDE SECTION PIN	2 \$	6.00	? X new
14	REAR BUMPER GUIDE SECTION - RH	\$	44.00	? X new
15	REAR BUMPER SENSOR <i>1 piece damaged</i>	2 TBC		
16	REAR BUMPER SENSOR SEAL RING <i>new</i>	4 \$	14.00	✓
17	REAR SILENCER - RH	\$	873.00	+
18	REAR SILENCER DUAL CLIP	\$	48.00	+
19	REAR SILENCER BRACKET	\$	41.00	+
20	REAR EXHAUST CHROME TRIM - RH	TBC		+
21	SUNDRIES	\$	400.00	? 19.20
TOTAL SPARE PARTS CHARGES		\$	8,514.00	
TOTAL LABOUR CHARGES		:	\$ 4,632.00	
GRAND TOTAL		\$	13,146.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0512/2020/TF 4-Aug-20 Glory Tan 1 OF 1 SKE 290 Y Audi A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	Rear bumper sensor socket <i>New</i>	\$ 16.00	✓ 12.24
2	Acrylic sealant	\$ 180.00	✓ 180
3	Cavity wax <i>New</i>	\$ 140.00	✓ 140
4	Stone chip	\$ 180.00	✓ 180
5	Rhs tail lamp panel <i>Dented</i>	\$ 162.00	✓ 129.2
Labours			
1	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	s/n \$ 480.00	✓ ✓
2	To cut out and weld rhs tail lamp panel. To repair rhs rear inner connecting plate.	\$ 3,200.00	1500 ✓
3	To respray rhs tail lamp panel, rhs rear inner connecting plate and rear end panelling. To carry out shop chip treatment and joint sealant works.	\$ 2,400.00	1100 ✓
TOTAL		\$ 6,758.00	

For Premium Automobiles Pte Ltd

Adrian Ling
06/08/20
Add 5 days

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 24/07/20.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant