

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 41055

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0487/2020/NS
Date : 13-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SLB 2628 Z

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

A16

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms Ho Lai Fong
Address : Blk 110 Rivervale Walk
#06-08
Singapore 540110
Telephone : HP +65 91181997
Type of Claim : ~~Third Party Claim~~ OD Claim
Policy No. : 2100479612-03
Vehicle No : **SGR 6336 P**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Aug-16
Engine No : CVN 015315
Chassis No : WAUZZZF40HA008792
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Jul-20
Place of Accident : Junction Of AMK Central 2 & Small Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGR 6336 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	X
2	To remove and transfer rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00	✓
3	To dismantle and reinstall rear bumper. To repair rhs rear fender. To renew rhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	1000 ✓
4	To respray rear bumper, rhs rear fender, rhs rear door and door handle.	\$ 3,000.00	1200 ✓ 550 x 2 = 1100 Handle = 100
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,282.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGR 6336 P

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR DOOR - RH <i>Dented</i>	\$	2,243.00	✓ 1794.40
2	REAR DOOR OUTER SEAL - RH <i>NE</i>	NEC \$	193.00	✓ 154.40
3	BONDING AGENT <i>NE NE</i>	NEC \$	46.00	✓ X
4	CLEANING SOLUTION <i>NE NE</i>	NEC \$	64.00	✓ X
5	SEALING STRIP <i>NE</i>	\$	16.00	X
6	SUNDRIES <i>NE</i>	\$	300.00	✓ 11.44 ✓
TOTAL SPARE PARTS CHARGES		:	\$ 2,862.00	
TOTAL LABOUR CHARGES		:	\$ 6,282.00	
GRAND TOTAL		:	\$ 9,144.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 24/07/201
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 05 Days.
H/S.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0487/2020/NS 6-Aug-20 Glory Tan 1 of 1 SGR 6336 P WAUZZZF40HA008792
--	---	--

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Rear door rhs door catch <i>Damaged</i>	\$ 119.00	✓ 94.50
<u>Labours</u> 1	To respray rhs sill panel.	\$ 700.00	550.00 X
TOTAL		\$ 819.00	

For Premium Automobiles Pte Ltd

Adrian Ling
06/08/20

Authorised Signature