

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: EQ	DATE	: 22/07/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: TP CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMS8374P	Cecilia	
MODEL	: HONDA FREED 1.5G A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 22/07/2020
		TIME	: 08:10HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,460.30	\$ 1,460.30 1208
2	TAIL GATE LOGO	1	\$ 72.30	\$ 72.30
3	TAIL GATE EMBLEM 'FREED' <i>tailgate emblem "freed"</i>	1	\$ 76.40	\$ 76.40
4	TAIL GATE EMBLEM 'HYBRID' <i>tailgate emblem "hybrid"</i>	1	\$ 76.40	\$ 76.40
5	TAIL GATE INNER HOLDER <i>tailgate inner holder</i>	1	\$ 80.00	\$ 80.00
6	TAIL GATE INNER TRIM <i>tailgate inner trim</i>	1	\$ 460.00	\$ 460.00
7	TAIL GATE TOP LOCK <i>tailgate top lock</i>	1	\$ 255.90	\$ 255.90
8	TAIL GATE WEATHERSTRIP <i>tailgate weatherstrip</i>	1	\$ 241.70	\$ 241.70
9	TAIL GATE LAMP RH <i>tailgate lamp</i>	1	\$ 380.20	\$ 380.20
10	TAIL GATE WINDSCREEN MOULDING <i>tailgate windscreen</i>	1	\$ 194.20	\$ 194.20
11	REAR BUMPER <i>Dented</i>	1	\$ 1,155.60	\$ 1,155.60 955
12	REAR BUMPER SIDE RETAINER <i>tailgate side</i>	2	\$ 69.70	\$ 139.40
13	REAR END PANEL (OUTER) <i>tailgate panel</i>	1	\$ 655.50	\$ 655.50
14	REAR END PANEL TOP GARNISH <i>tailgate garnish</i>	1	\$ 190.00	\$ 190.00

15 Rear Bumper Bracket x02
Caused 65 x 2 = 130

TOTAL PRICE \$ 5,437.90
 LESS 20% \$ 1,087.58
SUB TOTAL PRICE \$ 4,350.32

SPECIAL NETT ITEMS

3882.80

3066.24

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Debond</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE INNER TRIM CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
4	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
5	REAR END PANEL INSULATOR SEAL(OUTER) <i>2 x 1/2"</i>	1	\$ 120.00	\$ 120.00
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>1/2"</i>	1	\$ 20.00	\$ 20.00
7	REAR REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

Pass Buyer Bracket

Ortad

~~2~~ TOTAL ~~65~~ *350* ~~130.00~~ 530.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,400.00	<i>600</i>	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,400.00	<i>600</i>	
3	TO APPLY RUST PROOFING/ UNDER COAT	\$ 250.00	<i>30</i>	
4	WIRNING, BULB CHECKING	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR	\$ 250.00	<i>60</i>	
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>	
7	tailgate mechanism TO TRANSFER TAIL GATE MECHANISM	\$ 80.00	<i>✓</i>	
8	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>	
9	remove & refix rear reverse camera & distance setting REMOVE AND REFIX REAR REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>	

1820

TOTAL

\$3,740.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,880.32

TOTAL LABOUR COST : \$ 3,740.00

TOTAL REPAIR COST : \$ 8,620.32

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

L/S 23/07/20

0 \$ Days.

total: 8036.24

L/S: AK

(AK)