

REPAIR ESTIMATE*

VEHICLE NO SHA1863U

DATE 22.07.2020

MAKE :

MODEL : HYUNDAI IONIQ G2

CHINA / CHIANG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$418.30
1	FRONT BUMPER BRACKET LH			\$28.00
1	HEAD LAMP LH			\$1,198.80
1	FRONT BUMPER BRACKET TOP LH			\$35.00
1	FRONT FENDER LH			\$490.70
1	FRONT FENDER LH RETAINER			\$41.40
1	EMBLEM -BLUE DRIVER LH			\$26.60
1	WHEEL CAP LH			\$346.40
SUB TOTAL				\$2,585.20
LESS 20%				\$517.04
DISCOUNTED TOTAL				\$2,068.16
				Nett
Labour Charge				
Panel Beating				\$640.00
Spray Painting Charge				\$500.00
WIRING				\$60.00
TOTAL LABOUR				\$1,200.00
ESTIMATE TOTAL				\$3,268.16

Tanjin 97495746
 WP 23/7/20 @ 4pm
 P/P Beating before paint
 Tanjin @ (hand) on
 • 2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is...

A member of COMFORTDELGRO

Date/Time: 23.07.2020 11:20

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305412524

STOMER

REGN NO:

SHA1863U

MILEAGE

/MS

COMFORT TRANSPORTATION PTE LTD

MAKE :

HYUNDAI

FUEL

STOMER NO

7010045

E.....1/2.....F

DRESS

383 SIN MING DRIVE
 Singapore SINGAPORE 575717

MODEL

IONIQ(G2)

DATE/TIME IN
 23.07.2020 09:45

(R)

65508755

(O)

YR OF MANU.

17.07.2019

TARGET DATE

(P)

CHASSIS CODE

KMHC851CVKU164726

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 22.07.2020

NATURE: 3P 22.07.2020

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SHA1863U

CHIANG

Vehicle No.:

SHA1863U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard