

ATTN:		CHASSIS NUM:	1 3 27	
NO.	DESCRIPTION - PARTS	QTY	PRICE	
1	BONNET <i>un X</i>	1		
2	BONNET LOCK <i>un X</i>	1		
3	BONNET CATCH <i>un X</i>	1		
4	BONNET INSULATOR <i>un X</i>	1		
5	BONNET HINGE (L+R) <i>un X</i>	2		
6	BONNET STOPPER (L+R) <i>un X</i>	2		
7	BONNET LOGO (TOYOTA) <i>un X</i>	1		
8	HEADLAMP (L+R) <i>N/S one 1pc</i>	2		
9	HEADLAMP BRACKET (L+R) <i>un X</i>	2		
10	FRONT GRILLE <i>one</i>	1		
11	FRONT GRILLE CHROME <i>Scr</i>	1		
12	FRONT BUMPER <i>De/lor</i>	1		
13	FRONT BUMPER RETAINER (L+R) <i>un X</i>	2		
14	FRONT BUMPER REINFORCEMENT BAR <i>R X</i>	1		
15	FRONT BUMPER BRACKET (L+R) <i>un X</i>	2		
16	FRONT BUMPER BEAM <i>R X</i>	1		
17	FRONT BUMPER SPONGE <i>Torn</i>	1		
18	FRONT BUMPER GRILLE <i>un X</i>	1		
19	FRONT BUMPER TOWING CAP <i>un X</i>	1		
20	FRONT BUMPER FOG LAMP SIDE GARNISH (L+R) <i>N/S, Torn 1pc</i>	2		
21	FRONT BUMPER FOG LAMP SIDE GARNISH CHROME (L+R) <i>un X</i>	2		
22	FRONT BUMPER FOG LAMP GARNISH (L+R) <i>un X</i>	2		
23	FRONT BUMPER UNDERCOVER <i>un X</i>	1		
24	FRONT FENDER (L+R) <i>un X</i>	2		
25	FRONT FENDER COWLING (L+R) <i>un X</i>	2		
26	FRONT SUPPORT PANEL <i>R X</i>	1		
27	FRONT SUPPORT PANEL TOP GARNISH <i>un X</i>	1		
28	AIR CON CONDENSOR <i>un X</i>	1		
29	HIGH PRESSURE HOSE <i>un X</i>	1		
30	LOW PRESSURE HOSE <i>un X</i>	1		
31	RADIATOR <i>un X</i>	1		
32	DISCHARGE PIPE <i>un X</i>	1		
33	SUCTION PIPE <i>un X</i>	1		
34	RADIATOR FAN COWLING <i>un X</i>	1		
35	RADIATOR FAN BLADE <i>un X</i>	1		
36	RADIATOR FAN MOTOR <i>un X</i>	1		
37	WIPER WASHER TANK <i>un X</i>	1		
38	WIPER WASHER MOTOR <i>un X</i>	1		
SUBTOTAL			\$	-

		LESS 25%		\$ -
		PARTS TOTAL		\$ -
SPECIAL NETT			QTY	PRICE
1	BONNET INSULATOR CLIP	11X	10	\$ 100.00
2	FRONT BUMPER CLIP	11 50	10	\$ 100.00
3	FRONT CARPLATE	50X	1	\$ 120.00
4	FRONT CARPLATE FRAME	11X	1	\$ 120.00
5	FRONT FENDER COWLING CLIP	11X	10	\$ 100.00
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS	11X	10	\$ 100.00
7	RADIATOR COOLANT	11X	1	\$ 120.00
8	AIRCON GAS	11X	1	\$ 100.00
		SPECIAL NETT TOTAL		\$ -
LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	300	1	\$ 2,700.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	400	1	\$ 2,700.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	11X	1	\$ 400.00
4	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	11X	1	\$ 800.00
5	TO RNR A/C CONDENSOR ASSY	100	1	\$ 300.00
6	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11X	1	\$ 300.00
7	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	20	1	\$ 150.00
8	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X	1	\$ 600.00
9	TO DO WATER LEAK TEST .	11X	1	\$ 100.00
		TOTAL		\$ 8,050.00
		GRAND TOTAL COST		\$ 8,050.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: