



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com

Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:

SLJ 4436 E

MAKE & MODEL:

TOYOTA WISH

MILEAGE:

TYRE:

CHASSIS NUM:

Not Authorized
LHR
1/6 2500
2nd m/s.
27/7/20

U/MC

ATTN: HSIAO Tony

1/5 \$ 2500

Taken to Police Station

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	BONNET	1	\$ 1696.00
2	BONNET LOCK	1	\$ 331.00
3	BONNET CATCH	1	\$ 105.00
4	BONNET INSULATOR	1	\$ 420.00
5	BONNET HINGE (L+R)	2	\$ 396.00
6	BONNET STOPPER (L+R)	2	\$ 82.00
7	BONNET LOGO (TOYOTA)	1	\$ 115.00
8	HEADLAMP (L+R)	2	\$ 3378.00
9	HEADLAMP BRACKET (L+R)	2	\$ 460.00
10	FRONT GRILLE	1	\$ 692.00
11	FRONT GRILLE CHROME	1	\$ 305.00
12	FRONT BUMPER	1	\$ 1078.00
13	FRONT BUMPER RETAINER (L+R)	2	\$ 392.00
14	FRONT BUMPER REINFORCEMENT BAR	1	\$ 872.00
15	FRONT BUMPER BRACKET (L+R)	2	NIL
16	FRONT BUMPER BEAM	1	NIL
17	FRONT BUMPER SPONGE	1	\$ 311.00
18	FRONT BUMPER GRILLE	1	\$ 473.00
19	FRONT BUMPER TOWING CAP	1	\$ 105.00
20	FRONT BUMPER FOG LAMP SIDE GARNISH (L+R)	2	\$ 498.00
21	FRONT BUMPER FOG LAMP SIDE GARNISH CHROME (L+R)	2	NIL
22	FRONT BUMPER FOG LAMP GARNISH (L+R)	2	\$ 524.00
23	FRONT BUMPER UNDERCOVER	1	\$ 575.00
24	FRONT FENDER (L+R)	2	\$ 1966.00
25	FRONT FENDER COWLING (L+R)	2	\$ 486.00
26	FRONT SUPPORT PANEL	1	\$ 1089.00
27	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 394.00
28	AIR CON CONDENSOR	1	\$ 1292.00
29	HIGH PRESSURE HOSE	1	\$ 423.00
30	LOW PRESSURE HOSE	1	\$ 391.00
31	RADIATOR	1	\$ 1542.00
32	DISCHARGE PIPE	1	\$ 273.00
33	SUCTION PIPE	1	\$ 281.00
34	RADIATOR FAN COWLING	1	\$ 955.00
35	RADIATOR FAN BLADE	1	\$ 145.00
36	RADIATOR FAN MOTOR	1	\$ 879.00
37	WIPER WASHER TANK	1	\$ 154.00
38	WIPER WASHER MOTOR	1	\$ 389.00
SUBTOTAL			\$ -

65

65

P: \$ 5616
-25% = \$ 4212



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLJ 4436 E
TOYOTA WISH

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT BUMPER INNER FOG LAMP GARNISH (LH) n1	1	\$272.00
2	FRONT BRACE PANEL 12.10 bent	1	\$897.00
	P: \$1169 SUBTOTAL		\$ -
	-25% = \$476.75 LESS 25%		\$ -
	PARTS TOTAL		\$ -
	SPECIAL NETT	QTY	PRICE
	SPECIAL NETT TOTAL		\$ -
	LABOUR	QTY	PRICE
	TOTAL		#REF!
	GRAND TOTAL COST		#REF!

P: \$5088.75
S/N: \$50
L: \$820
Total: \$5958.75
-20% = \$4800

P: 4298.50
25%
3223.87
3275

P: 3026.50
25%
P: 2269.87
S.N - 50
L - 820
3139.87
22
2511

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

		LESS 25%		\$	-	
		PARTS TOTAL		\$	-	
		SPECIAL NETT	QTY	PRICE		
1	BONNET INSULATOR CLIP	11X	10	\$	100.00	X
2	FRONT BUMPER CLIP	11 50	10	\$	100.00	50
3	FRONT CARPLATE	8VCX	1	\$	120.00	X
4	FRONT CARPLATE FRAME	11X	1	\$	120.00	X
5	FRONT FENDER COWLING CLIP	11X	10	\$	100.00	X
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS	11X	10	\$	100.00	X
7	RADIATOR COOLANT	11X	1	\$	120.00	X
8	AIRCON GAS	11X S/N: 950	1	\$	100.00	X
		SPECIAL NETT TOTAL		\$	-	
		LABOUR	QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	300	1	\$	2,700.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	400	1	\$	2,700.00	
3	TO RUST PROOF ACCIDENT AFFECTED AREA	11X	1	\$	400.00	
4	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	11X	1	\$	800.00	
5	TO RNR A/C CONDENSOR ASSY	100 42X	1	\$	300.00	
6	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11X	1	\$	300.00	
7	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	20	1	\$	150.00	
8	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	11X	1	\$	600.00	
9	TO DO WATER LEAK TEST.	11X	1	\$	100.00	
		1: 920				
		TOTAL		\$	8,050.00	
		GRAND TOTAL COST		\$	8,050.00	
		820				