

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Authorized
Returning Bepalm*

4 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____
Third Party

Date: 23.07.2020

Accident Date : 20.07.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Isuzu NH" Reg. No. GBK1268G SKM6589E Claiming Against Your Insured Reg. No. SLV4994Y			
1pc	Front Bumper		<i>B1</i> 785.00 ✓
1pc	Front Bumper Bracket LH		<i>B1</i> 174.00 ✓
1pc	Front Grille		<i>Sn</i> 785.00 X
1pc	Headlamp LH		<i>Mycm</i> 569.00 ✓
1pc	Headlamp Lower Rubber Seal		<i>D17</i> 20.00 ✓
1pc	Headlamp Side Bracket LH		<i>D11</i> 48.00 ✓
1pc	Front Signal Lamp LH		<i>B2</i> 162.00 ✓
1pc	Front Signal Lamp Wire Harness LH		<i>R</i> 295.00 X
1pc	Front Corner Panel LH		<i>M17</i> 310.00 ✓
1pc	Front Corner Panel Top Cover		<i>M14</i> 60.00 ✓
1pc	Front Wing Mirror (Round)		<i>M14</i> 145.00 ✓
1pc	Front Wing Mirror (Square)		<i>Sn</i> 195.00 X
1pc	Front Wing Mirror Stand Bracket		<i>B1</i> 315.00 ✓
1pc	Front Door LH		<i>B1</i> 1,420.00 ✓
1pc	Front Door Lower Hinge		<i>D17</i> 132.00 ✓
1pc	Front Door Weatherstrip		<i>W</i> 240.00 ✓
1pc	Front Door Trim Board Clips	4.50	<i>W</i> 45.00 X
10pcs	Front Door Lower Arch Panel Garnish		<i>W</i> 172.00 ✓
1pc	Front Door Lower Step Board		<i>Med W</i> 345.00 ✓
1pc	Front Door Frame Rubber Seal		<i>W</i> 195.00 ✓
1pc	Front Windscreen Lower Side Moulding		<i>M17</i> 102.00 ✓
1pc	Front Wheel Rim		<i>Sn</i> 285.00 X
1pc	Front Wheel Bearing		<i>NA</i> 175.00 X
1pc	Front Wheel Mud Flap		<i>R</i> 195.00 X
			7,169.00
	Less 15%		1,075.35
			6,093.65
	Front Number Plate		<i>Sn</i> 45.00 SN X
	Front Door Company Reg Lable		<i>Mc</i> 25Sn 45.00 SN
	Front Door Inner Sticker (Reflective)		<i>Mc</i> 20Sn 120.00 SN
	Front Door Body AD Sticker		<i>Mc</i> Bill 450.00 SN 7
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		150.00 601
		C/F	6,933.65

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 23.07.2020

Accident Date : 20.07.2020

承接汽车烧焊喷漆及
代理各种车辆赔偿

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Isuzu NH" Reg. No. GBK1268G SKM6589E Claiming Against Your Insured Reg. No. SLV4994Y		
		B/F	6,933.65
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60.00 <i>301</i>
	To Dismantle / Hi Pressure Press / Replace Wheel Bearing	<i>nn</i>	100.00 <i>X</i>
	To Conduct High Speed Balancing	<i>nn</i>	60.00 <i>X</i>
	To Conduct Computerize Wheel Alignment Test	<i>nn</i>	80.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Front Door Pillar, Inner Panel, Step Panel, Door Arch Panel and Parts Replacement		750.00 <i>5501</i>
	To Respray Affected Areas (2K - 2 Tone)		900.00 <i>6001</i>
		Total :	<u><u>8,883.65</u></u>

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: