



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMT5325X
Chassis No : JHMGK3850LS217953
Model : JAZZ 1.3LXR CVT 20YM (EURO 6)
Owner's Name : LOU KOK YONG
Ins Policy No. :
Date of Accident : 22/7/2020

Document No. : SQT20002261
Date : 22. Jul 2020
Customer No. : WZ1007
Svc Advisor : NG SIN HAI
Engine No : L13B15000731
Date | Time : 22. Jul 2020 7:54:22 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
04636-T5A-300ZZ	PANEL SETR.RR.OUTSIDE <i>bt</i>	1	585.30	25	438.97	30.73	469.70
74552-T5B-003	FENDER,R.RR.INNER ?	1	81.00	25	60.75	4.25	65.00
90601-S30-003	GROMMETCOWL TOP ?	4	2.10	25	6.30	0.44	6.74
91501-TR0-003	CLIP,INNER FENDER <i>re</i>	8	2.80	25	16.80	1.18	17.98
71501-T5A-J50ZH	FACE RR.BUMPER <i>scu</i>	1	693.70	25	520.27	36.42	556.69
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>re</i>	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER <i>re</i>	7	2.30	25	12.07	0.84	12.91
42700-T5S-M72	WHEEL,DISK AL 15X7 <i>scu</i>	1	457.20	25	342.90	24.00	366.90
73511-T5A-003	GLASSR.QUARTER <i>re</i>	1	157.60	25	118.20	8.27	126.47
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>re</i>	2	9.90	25	14.85	1.04	15.89
91501-T5A-003	CLIPQUARTER WINDSHIELD A <i>re</i>	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIPQUARTER WINDSHIELD B <i>re</i>	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C <i>re</i>	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>re</i>	2	60.00		120.00	8.40	128.40
Sum Item					1671.49	116.99	1,788.48
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS. <i>re</i>	1	250.00		250.00	17.50	267.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					430.00	30.10	460.10

Printed on 22/7/2020 8:09:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M260050223

Company Ref No: S60FC13809

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMT5325X
Chassis No : JHMGK3850LS217953
Model : JAZZ 1.3LXR CVT 20YM (EURO 6)
Owner's Name : LOU KOK YONG
Ins Policy No. :
Date of Accident : 22/7/2020

Document No. : SOT20002261
Date : 22. Jul 2020
Customer No. : WZ1007
Svc Advisor : NG SIN HAI
Engine No : L13B15000731
Date | Time : 22. Jul 2020 7:54:22 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	180.00	150	180.00	12.60	192.60
BOJSE	SEALANT FOR RHR FENDER	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	150	180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL.	1	3000.00	3250	3000.00	210.00	3210.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2500.00	1040	2500.00	175.00	2675.00
BOSUN	REMOVE AND RENEW RHR WHEEL	1	50.00		50.00	3.50	53.50
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	320.00		320.00	22.40	342.40
Sum Labor					7080.00	495.60	7,575.60

Survey By Rasul - Hp 90010068

Date & Time 03/08/2020 @ 1040

Excess _____

Status _____

Signature [Signature]

Resurvey before paint

7 days

Total Amount 9,181.49 642.69 9,824.18

Total (Inclusive of GST) 9,824.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 22/7/2020 8:09:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.