

Not Notified
 6/1/2020 @ 6750/h

AAD2007-094

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5860R

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

24 JUL 2020

SHC 5860R

VF1ABL15AUC281455

RENAULT

LATITUDE

23.7.2020

AIG

6/3/2015

	PART
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR RH
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER REFLECTOR LH
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	BUMPER BEAM BRACKET RH REAR
1	BUMPER BLOCK LH REAR
1	BUMPER BLOCK RH REAR
1	BUMPER HARNESS REAR
1	BOOT REAR
1	BOOT FINISHER
1	BOOT WHEATERSTRIP
1	BOOT REFLECTOR LAMP LH
1	BOOT REFLECTOR LAMP RH
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	BOOT STRUT LH
1	BOOT STRUT RH
1	BOOT HINGE LH
1	BOOT HINGE RH

	LIST
\$	B ₁ 561.70 —
\$	D ₁ 411.90 —
\$	C ₁ 98.10 —
\$	S ₁ 82.10 X
\$	S ₂ 59.80 X
\$	C ₁ 16.60 ✓
\$	S ₁ 80.80 X
\$	S ₂ 54.20 ✓
\$	C ₁ 16.60 —
\$	B ₁ 547.80 —
\$	B ₂ 114.50 —
\$	B ₃ 114.50 —
\$	S ₁ 76.50 X
\$	S ₂ 76.50 X
\$	S ₃ 301.10 X
\$	B ₁ 1,677.20 ✓
\$	S ₁ 344.70 X
\$	S ₂ 178.20 X
\$	C ₁ 277.70 —
\$	C ₂ 277.70 —
\$	R ₁ 82.40 —
\$	R ₂ 95.80 —
\$	S ₁ 145.10 X
\$	S ₂ 145.10 X
\$	R ₁ 254.20 X
\$	R ₂ 253.80 X

Trans-cab Auto Services Pte Ltd

AAD2007-094

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5860R

1	BOOT TRIM BOARD	\$	<i>SL</i>	611.00	X
1	BOOT LOCK LINKAGE HOLDER	\$	<i>SL</i>	99.50	X
1	BOOT LOCK	\$	<i>N</i>	246.60	X
2	BOOT RUBBER PLUG	\$	<i>SL</i>	139.30	X
1	BOOT SWITCH	\$	<i>SL</i>	113.00	X
2	LICENCE PLATE LAMP	\$	<i>SL</i>	26.30	X
1	TAILLAMP RH	\$	<i>CN</i>	401.40	✓
1	TAILLAMP PANEL RH	\$	<i>N</i>	401.40	X
1	TAILLAMP LH	\$	<i>CN</i>	401.40	✓
1	TAILLAMP PANEL LH	\$	<i>N</i>	401.40	X
1	OUTER PANEL REAR (End Panel)	\$	<i>R</i>	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>DI</i>	404.56	✓
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>K</i>	1,229.40	} X
1	SPARE WHEEL PANEL TRIM	\$	<i>SL</i>	612.21	
1	SPARE WHEEL PANEL BRACKET LH L70Y	\$	<i>N</i>	70.60	
1	SPARE WHEEL PANEL BRACKET RH L70Y	\$	<i>N</i>	69.20	
1	SPARE TYRE BOARD	\$	<i>SL</i>	680.90	
1	EXHAUST REAR	\$	<i>K</i>	5,263.60	
1	EXHAUST CAP REAR	\$	<i>N</i>	125.40	
TOTAL		\$		18,387.57	
10%		\$		1,838.76	
		\$		16,548.81	

Special Nett

1SET	PARKING AID	\$	<i>Shon</i>	700.00	<i>600.00</i>
1SET	REAR BUMPER CLIP	\$	<i>N</i>	75.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	<i>N</i>	55.00	} X
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>N</i>	60.00	
1SET	BUMPER RETAINER RH CLIP RR	\$	<i>N</i>	65.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>N</i>	60.00	
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>N</i>	65.00	
1SET	BUMPER LOWER REAR RIVET	\$	<i>N</i>	65.00	
1SET	BUMPER LOWER REAR CLIP	\$	<i>N</i>	75.00	✓
2	END PANEL SEAM SEALANT	\$	<i>N</i>	180.00	<i>300.00</i>

Trans-cab Auto Services Pte Ltd

AAD2007-094

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHC 5860R

1SET BOOT FINISHER CLIP	\$	nn	55.00	X
1 BOOT STICKER "Trans-cab"	\$	nn	80.00	30sn
1 EXHAUST MOUNTING REAR	\$	sn	60.00	X
1 BOOT STICKER "6555-3333"	\$	nn	80.00	30sn
1 BOOT TRIM BOARD CLIP	\$	nn	60.00	X
1 RENAULT TYRE RIM (ROUE 7J 16H)	\$	sn	385.00	X
1 RENAULT TYRE 215/60/16	\$	sn	330.00	X
1 TAILLAMP CLIP RH	\$	nn	40.00	5.00sn
1 TAILLAMP CLIP LH	\$	nn	40.00	5.00sn
1 Rear Bumper Protector	\$	sn	170.00	X
1SET Rear licence plate with holder	\$	sn	140.00	X
1SET REAR END PANEL INNER TRIM CLIP	\$	sn	55.00	X
TOTAL	\$		2,895.00	

TOTAL PARTS	\$	19,443.81
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$	4,500.00	800
----	----------	-----

To supply and re-do rear luggage floor panel
insulation padding.

\$	nn	380.00	X
----	----	--------	---

To transfer of rear luggage floor panel fittings,
attachment and perform water seepage test.

\$	nn	380.00	X
----	----	--------	---

To transfer of bootlid fittings, attachments and
perform water seepage test.

\$		170.00	60
----	--	--------	----

To repair and realign rear exhaust pipe.

\$	nn	170.00	X
----	----	--------	---

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$	nn	380.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5860R**AAD2007-094**

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	<i>bol</i>
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	<i>1100</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>bol</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>40</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	<i>bol</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To pull and jack out rear body panel and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i>	380.00	<i>X</i>

TOTAL \$ 12,340.00**Over All Total \$ 31,783.81**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(LUMP SUM) Repair Days**25 DAYS***7 days*