

Date: 25.07.2020
Vehicle No: SLU5870U
Model: TOYOTA SIENTA 1.5G CVT
Chassis: NSP1707077402-2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SMC4911A
Date of Accident: 21.07.2020

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR QUARTER PANEL LINER CLIPS RH	6	<i>na</i> \$5.50	\$33.00 ✓
2	REAR QUARTER PANEL RH	1		REPAIR
3	REAR SLIDING DOOR RH	1		REPAIR
SUB TOTAL				\$33.00
LESS 25%				-\$8.25
PARTS TOTAL				\$24.75

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST ACCIDENT AREAS & ETC.

\$300.00 *150/*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR QUARTER PANEL RH, REAR SLIDING DOOR RH & ETC.

\$500.00 *400/*

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

na \$80.00 X

LABOUR TOTAL \$880.00

TingAn TOTAL \$904.75

Not withonk
Return After Paint
2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

