

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55469
Date Estimated : 08/07/2020
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
CHEN KAI SAM
BLK 834 JURONG WEST STREET 81
#15-17

SINGAPORE 640834

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SML9735L	WBA2C720707A28326	27/06/2018	225XE	0

DESCRIPTION

To replace rear bumper, boot lid including to knock out tail panel and dented area caused by the accident

1700 2,975.00

To respray rear bumper, boot lid and tail panel

1731 2,686.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To remove and install rear windscreen glass to transfer from old to new boot lid

676.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

80/? 150.00

Total Labour 1: 7,470.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID	1	1,210.35	1,210.35
# REAR BUMPER PANEL PRIMED (PD torn)	1	1,045.45	1,045.45
RR BUMPER RH SIDE GUIDE	1	61.35	61.35
REAR BUMPER CARRIER	1	460.40	460.40
RR BUMPER LH INNER SIDE GUIDE	1	61.35	61.35
# LH GUTTER STRIP	1	53.30	53.30
# RR LH LIGHT IN THE TRUNK LID	1	262.15	262.15
RR RH LIGHT IN THE SIDE PANEL	1	374.45	374.45

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55469
Date Estimated : 08/07/2020
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SML9735L	WBA2C720707A28326	27/06/2018	225XE	0

DESCRIPTION	QTY	PRIC	VALUE
(DG) CLEANER R1 (100ML) <i>acc Xnn</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>acc Xnn</i>	2	131.55	263.10
(DG/SL) ADHESIVE PRIMER VP 206 (30ML) <i>acc Xnn</i>	1	27.85	27.85
Total Parts :			3,845.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date/Time 03/08/2020 @ 1100 Excess S\$ TBA

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90060068 Authorised Yes/No Yes

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR (Yes) No PML (Yes) No

Surveyor's E-mail _____

No. of Working Days Recommend 5-6 days

Resurvey before paint

13,008.05



Labour 1	:	7,470.00
Parts	:	3,845.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	792.11
Grand Total	:	12,108.01

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55469**
Date Estimated : **08/07/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
CHEN KAI SAM
BLK 834 JURONG WEST STREET 81
#15-17

SINGAPORE 640834

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SML9735L	WBA2C720707A283	27/06/2018	225XE	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 ✓ nec	2.70	3.00	0.00	8.10
# REAR BUMPER PANEL PRIMED (PDC) RPT X nn	1,045.45	1.00	0.00	1,045.45
# EXPANDING NUT ✓ nec	1.00	2.00	0.00	2.00
# RR LH LIGHT IN THE TRUNK LID RPT X nn	262.15	1.00	0.00	262.15
# RR LH LIGHT IN THE SIDE PANEL RPT X nn	374.45	1.00	0.00	374.45

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	1,692.15
Total Labour & Parts :	1,692.15

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: