

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 55469**
Date Estimated : **08/07/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
CHEN KAI SAM
BLK 834 JURONG WEST STREET 81
#15-17

SINGAPORE 640834

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SML9735L	WBA2C720707A283	27/06/2018	225XE	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper, boot lid and attachment parts to facilitates repair caused by the accident.	1,700.00	0.00	1,700.00
To respray rear bumper, and boot lid.	1,731.00	0.00	1,731.00
To carry out body cavity preservation. (Per panel).	100.00	0.00	100.00
To remove and install rear windscreen glass to transfer from old to new boot lid	676.00	0.00	676.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00	0.00	451.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0.00	150.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0.00	150.00
Sundries.	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	2.70	3.00	0.00	8.10
TRUNK LID	1,210.35	1.00	0.00	1,210.35
# REAR BUMPER PANEL PRIMED (PDC)	1,045.45	1.00	0.00	1,045.45
# EXPANDING NUT	1.00	2.00	0.00	2.00
# RR LH LIGHT IN THE TRUNK LID	262.15	1.00	0.00	262.15
# RR LH LIGHT IN THE SIDE PANEL	374.45	1.00	0.00	374.45

SUPPLEMENTARY ITEMS

Total Labour : 5,038.00
Total Parts : 2,902.50



Final Report

Total Labour & Parts :	7,940.50
Deduction for Excess :	500.00
Total Repair Costs less Excess:	7,440.50
GST @7%:	520.84
Grand Total :	<u>7,961.34</u>

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55469**
Date Estimated : **08/07/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
CHEN KAI SAM
BLK 834 JURONG WEST STREET 81
#15-17

SINGAPORE 640834

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SML9735L	WBA2C720707A283	27/06/2018	225XE	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	2.70	3.00	0.00	8.10
# REAR BUMPER PANEL PRIMED (PDC)	1,045.45	1.00	0.00	1,045.45
# EXPANDING NUT	1.00	2.00	0.00	2.00
# RR LH LIGHT IN THE TRUNK LID	262.15	1.00	0.00	262.15
# RR LH LIGHT IN THE SIDE PANEL	374.45	1.00	0.00	374.45

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	1,692.15
Total Labour & Parts :	1,692.15