



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3045241901	Date of Loss:	12/07/2020
Vehicle Reg. No.:	GBG3193X	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SEADRAGON TECHNOLOGIES PTE LTD		
Make/Model:	RENAULT KANGOO II, 1.5 D DCI EXPRESS (M)	Vehicle Reg. Date:	21/07/2017
Vehicle Colour:	WHITE	Chassis No:	VF1FW18H556657538
Engine No:	K9KB608D680034		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS		Amount
Parts	28,682.50	34,200.00
Miscellaneous Items		0.00
Labour		6,890.00
Paintwork Labour		0.00
Towing		0.00
Calculated Gross Total (S\$)	35,572.50	38,480.00
- Excess (S\$)		2,000.00
(S\$)		36,180.00
+ GST 7.00% (S\$)		2,532.60
Nett Amount (S\$)		38,712.60

This claim is handled by: **EDWIN YAP KIAT BENG**

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 24 Jul 2020)**Parts:** N/A RENAULT KANGOO II 1.5 D dCi Express (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sin Yew Hup Auto Pte Ltd/GBG3193X/24/07/2020 11:22**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / CRU	0.00	0.00	*760.00 F
2	2		*FRONT BUMPER SIDE HOLDER / CRU	0.00	0.00	*70.00 F
3	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	*1,050.00 F
4	8		*FRONT BUMPER CLIP / INK	0.00	0.00	*40.00 F
5	1		*FRONT GRILLE ? X SVC	0.00	0.00	*330.00 F
6	1		*FRONT GRILLE LOGO EMBLEM ? X SVC	0.00	0.00	*100.00 F
7	1		*FRONT FENDER RH / CRU	0.00	0.00	*380.00 F
8	1		*FRONT FENDER INNER SHIELD RH / Mis.	0.00	0.00	*170.00 F
9	10		*FRONT FENDER INNER SHIELD CLIP / NEC	0.00	0.00	*50.00 F
10	1		*FRONT FENDER INNER BRACKET RH ? / BT	0.00	0.00	*320.00 F
11	1		*BONNET X R	0.00	0.00	*830.00 F
12	1		*BONNET LOCK X SVC	0.00	0.00	*330.00 F
13	2		*BONNET HINGE X SVC	0.00	0.00	*160.00 F
14	1		*BONNET ABORBER RH X SVC	0.00	0.00	*230.00 F
15	2		*HEADLAMP RH / CRU LH / CRA	0.00	0.00	*750.00 F
16	1		*FRONT CHASSIS MEMBER RH ? X R	0.00	0.00	*900.00 F
17	1		*WASHER TANK / CRU	0.00	0.00	*145.00 F
18	1		*ACCUMULATOR DRIER / BT	0.00	0.00	*550.00 F
19	1		*INTERCOOLER ? / CRA	0.00	0.00	*690.00 F
20	1		*FRONT SUPPORT PANEL ? / CRU	0.00	0.00	*500.00 F
21	1		*RADIATOR ? / CRA	0.00	0.00	*1,000.00 F
22	1		*AIRCON CONDENSER ? X SVC	0.00	0.00	*800.00 F
23	1		*AIRCON DISCHARGE HOSE ? X SVC	0.00	0.00	*350.00 F
24	1		*AIRCON SUCTION PIPE ? / BT	0.00	0.00	*380.00 F
25	1		*FRONT LOWER ARM RH ? / BT	0.00	0.00	*380.00 F
26	1		*FRONT SHOCK ABSORBER RH / BT	0.00	0.00	*250.00 F
27	1		*FRONT KNUCKLE RH ? / BT	0.00	0.00	*480.00 F
28	1		*FRONT KNUCKLE BEARING RH ? / BT	0.00	0.00	*120.00 F
29	1		*FRONT DRIVE SHAFT RH / CRU	0.00	0.00	*850.00 F
30	1		*STEERING RACK & PINION ? X SVC	0.00	0.00	*1,395.00 F
31	1		*STEERING LINK RH ? X SVC	0.00	0.00	*155.00 F
32	2		*HUB CAP / SCR	0.00	0.00	*360.00 F
33	2		*STEERL RIM FR / BT RR X SVC	0.00	0.00	*440.00 F
34	1		*ENGINE CROSS MEMBER ? / BT	0.00	0.00	*1,200.00 F
35	1		*FRONT WINDSCREEN / CRA	0.00	0.00	*560.00 F
36	1		*FRONT WINDSCREEN MOULDING / NEC	0.00	0.00	*100.00 F
37	1		*STEERING AIRBAG / BK	0.00	0.00	*1,850.00 F
38	1		*PASSENGER AIRBAG / BK	0.00	0.00	*1,500.00 F
39	1		*AIRBAG ECU / NEC	0.00	0.00	*550.00 F
40	2		*FRONT IMPACT SENSOR / NEC	0.00	0.00	*520.00 F
41	1		*REAR BUMPER / CRU	0.00	0.00	*620.00 F
42	1		*REAR BUMPER SIDE HOLDER / CRU	0.00	0.00	*150.00 F
43	1		*REAR BUMPER MUDFLAP / PCH	0.00	0.00	*80.00 F
44	1		*REAR SHOCK ABSORBER RH ? X SVC	0.00	0.00	*160.00 F
45	1		*REAR AXLE ? / BT	0.00	0.00	*1,200.00 F

Sin Yew Hup Auto Pte Ltd/GBG3193X/24/07/2020 11:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

27/07/2020

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*REAR AXLE BEARING RH <i>DSVC</i>	0.00	0.00	*120.00F X
47	1		*REAR FENDER RH <i>pb</i>	0.00	0.00	*1,300.00F /
48	1		*DASHBOARD <i>CR4</i>	0.00	0.00	*850.00F /
F=Franchise part.						
Sub Total (S\$)						26,075.00
+ Margin on L,N Items 20.00 % (S\$)						5,215.00
10%						
Total Parts (S\$)						28,682.50 31,290.00

Sin Yew Hup Auto Pte Ltd/GBG3193X/24/07/2020 11:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

$$\begin{array}{r}
 19,945 \\
 + 10\% \\
 \hline
 P = 21,939.5 \\
 L = 4,250 \\
 \hline
 26,189.5 \\
 - 20\% \\
 \hline
 20,951.60
 \end{array}$$

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	120.00 ✓
2	TO DISMANTLE ALL DAMAGED PARTS, CUT/WELD FRONT CHASSIS RH, REAR FENDER RH, FRONT SUPPORT PANEL, PANEL BEAT / STRAIGHTEN ALL DENTS CHECK ADJUST, REPLACE AND RE-ALIGN THE ABOVE PARTS	New	3,000.00 1,600
3	TO PUTTY AND SPRAY PAINT BONNET, FRONT SUPPORT PANEL, FRONT FENDER RH, FRONT FENDER BRACKET RH, FRONT CHASSIS MEMBER RH, FRONT WHEELHOUSE RH, FRONT DOOR PILLAR RH, FRONT DOOR RH, REAR FENDER RH AND ALL AFFECTED PORTIONS	New	2,000.00 1,200
4	TO REMOVE AND REPLACE AIRBAGS AND RESET	New	350.00 200
5	TO REMOVE AND REPLACE DASHBOARD	New	250.00 200
6	TO REPLACE AIRCON CONDENSER AND REFILL GAS	New	120.00 ✓
7	TO REPLACE RADIATOR AND PRESSURE CHECK	New	120.00 ✓
8	TO REMOVE AND REFIT REAR FENDER INNER TRIMS, LININGS IN ORDER TO FACILITATE REPAIRS	New	120.00 80
9	TO REMOVE AND REPLACE FRONT RH UNDER CARRIAGE, ENGINE CROSS MEMBER AND DRIVE SHAFT RH	New	400.00 ✓
10	TO REMOVE AND REPLACE REAR AXLE AND RH UNDERCARRIAGE	New	350.00 150
11	TO CHECK WHEEL ALIGNMENT	New	60.00 ✓
Gross Labour Cost (S\$)			6,890.00 4,250

Sin Yew Hup Auto Pte Ltd/GBG3193X/24/07/2020 11:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Repair days - 14 days.

Excess : \$2000

Rev 7 00

L/S

After paint photo

27/07/2020

Sun Pin (LKB)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: