

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 30 Jul 2020

Preliminary Advice

Vehicle No	: GBG3193X	Accident Date	: 12/07/2020
Make	: RENAULT KANGOO II	Policy No.	: DMCVSN3045241901
Assignment Date	: 25/07/2020	Excess	: S\$2,000.00
Date of Inspection	: 27/07/2020	Est. Duration of Repair	: 14 days
Inspection At	: Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate Singapore 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,876.25
Revised Amount	:S\$	20,033.75
Check Items (Estimated)	:S\$	12,167.00
Total	:S\$	32,200.75
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	24,761.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,239.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer able to undertake the repair cost not exceeding L/S \$ 18,000.00.