



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim :	<u>THIRD PARTY</u>	Vehicle No. :	<u>FBL1477P</u>
		Make & Model :	<u>YAMAHA MT-09 ABS</u>
		Year of Manufacture :	<u>2016</u>
		Chassis No. :	<u>JYARN29S000004022</u>
Ins Company :	_____	Engine No. :	_____
Excess :	_____	Policy No. :	_____
Date of Accident :	<u>16/07/2020</u>	Time of Accident :	<u>08.35AM</u>
Suggested Days of Repair :	_____	<u>In-house Vehicle Assessor</u>	

Repair Estimates

Parts (a) Cost / List Price Items	_____
Plus/Less	_____
Total of Cost / List	=====
(b) Nett Price Items	_____
Less	_____
Total of Nett Item	=====
(c) Special Nett Items	\$ 2,500.00
Total Parts Cost (Appendix A)	\$ 2,500.00
Labour (Appendix B)	\$ 150.00
Total Repair Cost	\$ 2,650.00

Case Owner : _____

Signature : _____

Contact No

68485725 - JOHARI
68485726 - TINIE

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
Remarks By Surveyor		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:\$	_____
(e) Signature of surveyor	:	_____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : FBL1477P Case Owner : 0

Make & Model : YAMAHA MT-09 ABS Year Manufacture : 2016

Chassis No : JYARN29S000004022 Engine No : N701E062426

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : Third Party

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	SIREN ASSY	1				\$1,600.00	
2	FRONT CRASH BAR – LEFT	1				\$ 425.00	
3	FRONT CRASH BAR – RIGHT	1				\$ 425.00	
4	TOWING FROM ACCIDENT SCENE	1				\$ 50.00	
5	0	0					
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

