

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6 / A1620007690 / UKS3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 7086 B

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 10499

Veh No: SME 7086 B Yr Regn: 10 OF

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry

C.C

1998

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

161086

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR05313K4107035950

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55 R17

R:

BS / DUB / EXNOVA / GY / FS / EIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/7/20

D.O.I.

27/7/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

have SI involved coe 28-10-2023

have video of folder

Dispute. Rear bumper only.

15/8/20 P/P & 800 confirmed with Alan.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

note: Khanchana

FASTECH AUTO PTE LTD

1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

VEHICLE No: SME 7086B

Not Authorized
R/R
P/P ~~800~~ / 3 days.

1PC	REAR BUMPER
1PC	REAR BUMPER REINFORCEMENT
1PC	REAR BUMPER REFLECTOR O/S
1SET	REAR BUMPER CLIPS
1SET	REAR BUMPER REVERSE SENSOR
1PC	REAR END PANEL

R	\$545.10	X
R	\$365.20	X
11	\$68.10	X
11	\$50.00	X
311	\$265.00	X
R	\$619.20	X
	\$1,912.60	

(25%)

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$50.00	X
	\$80.00	✓
	\$600	300
	\$600.00	400
	\$3,292.60	
		800

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: