

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora_khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42923

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0519/2020/NS
Date	:	27-Jul-20

Vehicle IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tan Boon Choon Jayson
Address	:	Blk 44 Marine Crescent #14-12 Singapore 440044
Telephone	:	(HP) +65 96885520
Type of Claim	:	Own Damage Claim
Policy No.	:	2100478816-03
Vehicle No	:	SGU 9368 L
Model Code	:	A4 Sedan 1.4 TFSI S
Model / Year	:	16/8/2016
Engine No	:	CVN 016613
Chassis No	:	WAUZZZF44HA016457
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Jul-20
Place of Accident	:	Along Dunman Rd At Junc Of Carpmael Rd

Premium Automobiles

55-01, Road 1, Singapore 238896
Tel: +65 732 1141 Fax: +65 732 1145

Telefax:

Estimated Labour Charges for Accident Vehicle, SGU 9368 L

S/n	Nature of Jobs	S/N	\$	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N	\$	280.00	X
2	To carry out first measurement test on car o-liner.	S/N	\$	800.00	?
3	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N	\$	280.00	✓
4	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$	1,200.00	✓
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining and both curtain airbags.	S/N	\$	3,500.00	✓
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N	\$	2,800.00	?
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$	2,400.00	?
8	To place vehicle on car o-liner.	S/N	\$	1,800.00	?
9	To renew front windscreen.	S/N	\$	480.00	✓
SUB TOTAL LABOUR CHARGES				: \$ 13,640.00	

Premium Automobiles

N 100 Road 1, Singapore 408699
Tel: 5488 2121 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGU 9368 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
10	To install solar film for front windscreen.	S/N \$ 400.00 ✓	
11	To carry out windscreen water seepage test.	S/N \$ 200.00 ✓	
12	To remove and transfer both front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00 X	
13	To dismantle and reinstall both front door panel trims. To remove and reinstall both wing mirror assys.	S/N \$ 700.00 X	
14	To remove and transfer both headlight control units and power modules.	S/N \$ 700.00 ✓ 500.	
15	To dismantle and renew front bumper, bonnet, both front fenders, both headlights and both front doors. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed. ✓ ✓	\$ 7,000.00 ✓ 3250.	
16	To respray front bumper, both front fenders, bonnet hinges, both front upper A-pillars and both front doors. Bonnet X ✓	\$ 7,300.00 ✓ 2200.	
17	to carry out wheel alignment.	S/N \$ 280.00 ✓	
18	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		: \$ 31,164.00	

Premium Automobiles

55, Ubi Road 1, Singapore 408699
Tel : 6762421 Fax : 6711104

Telefax

Material List for Accident Vehicle Regn No. SGU 9368 L

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Disbled</i>	\$	2,111.00	✓
2	FRONT BUMPER FIXING PARTS <i>3 pcs</i>	\$	282.00	+
3	FRONT BUMPER SECURING STRIP	2	\$ 70.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	194.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	208.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 124.00	+
7	RADIATOR GRILLE <i>Crushed</i>	\$	1,139.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 268.00	+
9	FRONT BUMPER CARRIER <i>Best</i>	\$	795.00	✓
10	FRONT BUMPER FOAM FILLER PIECE <i>Crushed</i>	\$	123.00	✓
11	FOAM FILLER PIECE COVER <i>?</i>	\$	126.00	?
12	FRONT BUMPER GUIDE SECTION - LH <i>3 pcs</i>	\$	36.00	+
13	FRONT BUMPER GUIDE SECTION - RH	\$	37.00	+
14	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$ 450.00	?
15	CAUTION SIGN STICKER <i>Ne</i>	NEC	\$ 14.00	✓
16	AIRCON STICKER <i>Ne</i>	NEC	\$ 8.00	✓
17	LOCK CARRIER BRACKET <i>Crushed</i>	\$	136.00	✓
18	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 56.00	?
19	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	4	TBC	+
20	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 14.00	+
SUB TOTAL SPARE PARTS		:	\$ 6,191.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 9368 L

Parts Description			Damaged Parts & Prices	
S/N	Parts Description		S/Nett	Remarks
21	FRONT BUMPER WIRING SET	Alc ~	\$ 505.00	✓
22	HORN - LH HIGH TONE	?	\$ 124.00	✓
23	SPRING SHACKLE - LH	?	\$ 29.00	?
24	HORN - RH LOW TONE	?	\$ 124.00	?
25	SPRING SHACKLE - RH	?	\$ 29.00	?
26	FRONT FENDER - LH / RH	Distorted	2 \$ 1,516.00	✓
27	FRONT FENDER ATTACHMENT PARTS	?	\$ 200.00	?
28	FRONT FENDER CLOSING ELEMENT - LH / RH	2 \$	98.00	✓
29	FRONT FENDER BRACKET - LH / RH	?	70.00	?
30	DEFORMATION ELEMENT BRACKET - LH / RH	2 \$	98.00	✓
31	FRONT FENDER BRACKET	?	62.00	?
32	FRONT FENDER BRACE - LH / RH	?	234.00	?
33	WHEEL HOUSING LINER - LH / RH	2 \$	474.00	✓
34	WHEEL HOUSING LINER ATTACHMENT PARTS	2 \$	90.00	✓
35	WHEEL SPOILER - LH / RH	2 \$	146.00	✓
36	WHEEL SPOILER TRIM - LH	?	35.00	✓
37	WHEEL SPOILER TRIM - RH	?	36.00	✓
38	STONE CHIP GUARD - LH / RH	2 \$	100.00	✓
39	BONNET	Distorted	\$ 2,763.00	✓
40	BONNET ATTACHMENT PARTS	?	\$ 121.00	?
SUB TOTAL SPARE PARTS			: \$ 6,854.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 9368 L

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remarks	
41	BONNET LID HINGE - LH / RH	2 \$	?	602.00
42	BONNET IMPACT PROTECTION - CENTRE	\$	?	27.00
43	BONNET IMPACT PROTECTION - LH	\$	?	28.00
44	BONNET IMPACT PROTECTION - RH	\$	?	27.00
45	FENDER LEDGE TOP COVER - INNER	2 \$	?	122.00
46	FENDER LEDGE TOP COVER - UPPER	2 \$	?	62.00
47	FENDER LEDGE TOP COVER - LOWER	2 \$	?	46.00
48	BONNET GAS FILLED STRUT	2 \$	?	235.00
49	BONNET STRIKER - LH / RH	2 \$	?	100.00
50	BONNET LID LOCK	2 \$	?	423.00
51	BONNET BOWDEN CABLE - CENTRE	\$	?	57.00
52	BONNET BOWDEN CABLE	\$	?	57.00
53	BONNET RELEASE LEVER	\$	?	13.00
54	BONNET LID LOCK CABLE	\$	?	73.00
55	PLENUM CHAMBER COVER	\$	?	96.00
56	LED HEADLIGHT - LH / RH	2 \$	?	15,386.00
57	MAIN LIGHT ELECTRONICS POWER MODULE	2 \$	?	1,478.00
58	LIGHT CONTROL SYSTEM CONTROL UNIT	2 \$	?	1,484.00
59	HEADLAMP REPAIR KIT - LH / RH	2 \$	?	260.00
60	COMPENSATING PIECE	2 \$	?	79.00
SUB TOTAL SPARE PARTS		: \$ 20,655.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 9368 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
61	HEADLIGHT HOSE - LH / RH <i>nt n</i>	2 \$	72.00 <i>✓</i>
62	LIFT CYLINDER - LH / RH <i>"</i>	2 \$	416.00 <i>✓</i>
63	LIFT CYLINDER BRACKET <i>?</i>	2 \$	12.00 <i>✓</i>
64	LIFT CYLINDER CORRUGATED PIPE <i>nt n</i>	\$	92.00 <i>✓</i>
65	LOCK CARRIER <i>Carld</i>	\$	1,004.00 <i>✓</i>
66	COOLANT REGULATOR SUPPORT <i>nt</i>	2 \$	75.00 <i>✓</i>
67	AIRCON CONDENSER <i>Dentld</i>	\$	615.00 <i>✓</i>
68	REFRIGERANT LINE <i>?</i>	\$	165.00 <i>✓</i>
69	REFRIGERANT LINE <i>?</i>	\$	336.00 <i>✓</i>
70	HIGH PRESSURE SAFETY SWITCH VALVE <i>nt n</i>	\$	49.00 <i>✓</i>
71	REFRIGERANT LINE PRESSURE SENSOR <i>nt n</i>	\$	186.00 <i>✓</i>
72	REFRIGERANT LINE <i>nt n</i>	\$	245.00 <i>✓</i>
73	EXTERNAL TEMPERATURE SENSOR <i>"</i>	\$	56.00 <i>✓</i>
74	EXTERNAL TEMPERATURE SENSOR BRACKET <i>Carld</i>	\$	18.00 <i>✓</i>
75	RADIATOR <i>?</i>	\$	647.00 <i>✓</i>
76	RADIATOR RUBBER BUSH - LOWER <i>"</i>	2 \$	18.00 <i>✓</i>
77	RADIATOR RUBBER BUSH - LOWER <i>?</i>	2 \$	24.00 <i>✓</i>
78	ADDITIONAL RADIATOR - LOWER CENTRE <i>nt n</i>	\$	505.00 <i>✓</i>
79	READY MIX COOLANT <i>nt n</i>	\$	91.00 <i>✓</i>
80	RADIATOR FAN RING <i>?</i>	\$	242.00 <i>✓</i>
SUB TOTAL SPARE PARTS		: \$	<u>4,868.00</u>

Premium Automobiles

55, Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 9368 L

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
81	RADIATOR FAN	1,896.00	✓
82	RADIATOR AIR GUIDE - LH / RH <i>2</i>	56.00	✓
83	RADIATOR AIR GUIDE - LH / RH <i>2</i>	24.00	✓
84	RADIATOR AIR GUIDE - UPPER <i>and</i>	16.00	✓
85	RADIATOR AIR GUIDE - LOWER <i>?</i>	22.00	✓
86	AIR INTAKE AIR DUCT - RH <i>and</i>	22.00	✓
87	AIR INTAKE AIR GUIDE <i>and</i>	53.00	✓
88	AIR INTAKE HOSE <i>?</i>	94.00	✓
89	AIR INTAKE AIR FILTER <i>?</i>	382.00	✓
90	HOSE CLAMP <i>per</i>	12.00	+
91	AIR INTAKE CONNECTION <i>per</i>	596.00	+
92	INTER COOLER GASKET <i>per</i>	13.00	+
93	CHARGE AIR COOLER <i>per</i>	718.00	+
94	INTER COOLER SEAL <i>per</i>	16.00	+
95	INTER COOLER GASKET <i>per</i>	13.00	+
96	THROTTLE VALVE ADAPTER <i>per</i>	1,100.00	+
97	THROTTLE BODY GASKET	16.00	+
98	RETAINING BAR <i>per</i>	15.00	+
99	FRONT DOOR - LH <i>per</i>	2,354.00	+
100	FRONT DOOR OUTER SEAL <i>per</i> NEC	203.00	+

SUB TOTAL SPARE PARTS : \$ 7,621.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 63662323 Fax: 68411183

Telefax

Material List for Accident Vehicle Regn No. SGU 9368 L

S/N		Parts Description	Damaged Parts & Prices		Remarks
			S/Nett		
101	BONDING AGENT	3 New	NEC \$	47.00	✓
102	CLEANING SOLUTION		NEC \$	65.00	✓
103	FRONT DOOR - RH	NEU	\$	2,354.00	✓
104	FRONT DOOR OUTER SEAL - RH	NEU	NEC \$	203.00	✓
105	BONDING AGENT	3	NEC \$	47.00	✓
106	CLEANING SOLUTION	NEU	NEC \$	65.00	✓
107	FRONT DOOR CATCH		2 \$	208.00	✓
108	WINDOW SLOT SEAL - LH / RH	Cut	2 \$	606.00	✓
109	WINDOW GUIDE TRIM STRIP - LH / RH	NEU 2	\$	508.00	✓
110	WINDSCREEN	Cracked	\$	1,125.00	✓
111	RAIN SENSOR	NEU NEU	\$	751.00	✓
112	PRIMER	NEU	\$	19.00	✓
113	WATER DEFLECTOR STRIP - LH / RH	NEU 2	\$	132.00	✓
114	STEERING WHEEL AIRBAG	} Adjusted 3	\$	3,382.00	✓
115	AIR BAG UNIT		\$	4,324.00	✓
116	HEAD AIRBAG UNIT - LH / RH		2 \$	3,684.00	✓
117	AIRBAG CRASH SENSOR - FRONT			TBC	✓
118	AIRBAG CONTROL UNIT		\$	2,088.00	✓
119	SEAT BELT - LH		\$	1,056.00	✓
120	SEAT BELT		\$	1,091.00	✓
SUB TOTAL SPARE PARTS			: \$ 21,755.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGU 9368 L

			<u>Damaged Parts & Prices</u>	
S/N	Parts Description		S/Nett	Remarks
121	SEAT BELT HEIGHT ADJUSTER	?	2 \$	332.00 ?
122	STEERING WHEEL <i>Not In</i>		\$	2,216.00 X
123	DASHBOARD <i>Torn</i>		\$	5,229.00 ✓
124	WINDSCREEN DEFROSTER NOZZLE <i>Not In</i>		\$	166.00 ✓
125	DASHBOARD TOP COVER ?		\$	122.00 ✓
126	MOULDED HEADLINING <i>Cracked</i>		\$	1,896.00 ✓
127	A-PILLAR TRIM - LH / RH <i>Rehnd</i>	2	\$	404.00 ✓
128	B-PILLAR TRIM - LH / RH ?	2	\$	464.00 ?
129	C-PILLAR TRIM - LH / RH <i>Not In</i>	2	\$	428.00 ✓
130	D-PILLAR TRIM - LH / RH	2	\$	456.00 ✓
131	FRONT FOLDING GRAB HANDLE ?	2	\$	279.00 ?
132	REAR FOLDING GRAB HANDLE - LH / RH <i>Not In</i>	2	\$	280.00 ✓
133	FRONT NO PLATE <i>Not In</i>	S/N	\$	60.00 ✓
134	WINDSCREEN SEALANT <i>Not In</i>	S/N	\$	200.00 ✓
135	SUNDRIES	?	\$	600.00 ?
TOTAL SPARE PARTS			:	\$ 81,076.00
TOTAL LABOUR CHARGES			:	\$ 31,164.00
GRAND TOTAL			:	\$ 112,240.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian Lij
28/07/20

Not Authorised, 15 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant