

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST170/20/CIS
Your Ref: To be advised

25-Jul-20

China TaiPing Insurance (S) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Shirley

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimate cost of repair to Isuzu NHR85 no: YN2735E

Date of accident: 21-07-2020

Parts supply:

2 pcs Taillamps @\$252.00 *Est*
2 pcs Taillamp brackets @\$186.00 *new*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

504	504.00	✓
428.40	372.00	+
	876.00	
Less 15%:	(131.40)	

S/Nett Items

2 pcs Taillamp wiremesh @\$100.00 (S/Nett) *LH set*
1 set Rear reverse sensor (S/Nett) *Payd*
1 pc Rear reverse sensor holder base *confd*
2 pcs Stoppers @\$60.00 (S/Nett) *LH could*
2 pcs Rear side stoppers @\$50.00 (S/Nett) *new*
1 pc Rear no. plate (S/Nett) *new*
1 pc Rear no. plate bracket (S/Nett) *new*
1 pc Rear bumper (S/Nett) *Best*
2 pcs Rear bumper brackets @\$150.00 (S/Nett) *Best*
1 pc Rear lock bar (S/Nett) *Best*
1 pc Rear lock bar bracket (S/Nett) *new*
1 pc Rear compartment door R/h (S/Nett) *Payd*
1 pc Rear compartment door sticker - Certis CISCO (S/Nett) *3 new*
1 pc Rear compartment door sticker - ANTI-HIJACK (S/Nett) *3 new*
1 pc Rear compartment door sticker - AUXILIARY POLICE (S/Nett) *new*
1 pc Rear R/h compartment door sticker - 60km/h (S/Nett) *3 new*
1 pc Rear R/h compartment door emblem - Green disc (S/Nett) *3 new*

200.00	- / 20
350.00	- 200
200.00	- 150
120.00	- 60
100.00	+
35.00	+
120.00	+
350.00	-
300.00	-
280.00	-
60.00	+
650.00	+
100.00	- 80
100.00	- 80
100.00	- 80
10.00	✓
30.00	✓
3,849.60	

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.
To respray affected part.
To apply underseal.
To remove & refit rear reverse sensor
To remove & refit of wirings.

Adrian Lij
1/2 28/07/20
04 days

1110	650.00	400
	750.00	600
	60.00	40
	60.00	40
	30.00	✓
SS	5,399.60	

total: 3258.40
1/2 2.6K