

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 29 Jul 2020

Preliminary Advice

Vehicle No	: GBF1716G	Accident Date	: 24/07/2020
Make	: NISSAN NV350	Policy No.	: Z19VC05003009
Assignment Date	: 27/07/2020	Excess	: S\$2,200.00
		Additional Excess	: S\$40,000.00
Date of Inspection	: 28/07/2020	Est. Duration of Repair	: 14
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,548.65
Revised Amount	:S\$	13,425.65
Check Items (Estimated)	:S\$	5,163.50
Total	:S\$	18,589.15
 Lump Sum Repair	 :S\$	 11,300.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	28,695.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,305.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
REPAIRER ABLE TO REPAIR THE VEHICLE AT LUMP SUM \$11,300.00.