

ASS. REC. BY:

Steve

REF:

CS/LPC 2000 7724 / Eqf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. Z19VC05003009

Claims No. 19/20/20/VC05/023492

Sum Insured: Excess: 2200

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

GBF17166

Yr Regn:

27/7/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350

c.c. 2488

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

187317

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1MC 2E262-0006793

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

11

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/7/20

D.O.I.

28/7/20

Survey held at

Ken Fook Sing Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-40K

PV-28695

NV-11305

29/07/20@11.15am revert to Ong Li Li via Merimen. (repairer asking LS \$12K)

29/07/20@4.25pm Chew Beng Kee informed C/A at Lump Sum \$11300 via Merimen.

29/07/20@5.20pm Informed Mr Tan C/A not more than LS \$11300 & ex:\$2200 by email.

29/09/20@4.21pm confirmed with Mr Tan LS \$11300, 14 days (Red \$11410.15, 50%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 29/09 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Form: MER-OD

Lump Sum: 11300



簡福星時時工廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 639147
 Tel : (65) 6747 9660, 6858 2126, 6858 4361
 Fax : (65) 6748 1006, 6281 8428
 E-mail: kanta@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No: Z21888-00E
 GST Reg. No: M9-0005333-E

INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z19VC05003009	Date of Loss:	24/07/2020
Vehicle Reg. No.:	GBF1716G	Driveable?	
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	DALE ENTERPRISE		
Driver:	TAN TUAN YEOW (CHEN CHUANYAO)		
Make/Model:	NISSAN NV350, 2.5 5AT 5DR EURO V (A)	Vehicle Reg. Date:	27/07/2016
Vehicle Colour:	METALLIC BLACK	Chassis No:	JN1MC2E26Z0006703
Engine No:	YD25398726A		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	21		
Description of Accident/Loss	REFER WITH ATTACH.		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	16,503.65
Miscellaneous Items	95.00
Labour	3,350.00
Paintwork Labour	1,600.00
Towing	0.00
Gross Total (S\$)	21,548.65
+ GST 7.00% (S\$)	1,508.41
Nett Amount (S\$)	23,057.06

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS
Reference

Part Source: (Last Synchronised: 27 Jul 2020)
Parts: N/A NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/GBF1716G/27/07/2020 15:46
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ROOF LINING / CR4	0.00	0.00	*980.00 F
2	1		*FRONT WINDSCREEN GLASS / BR	0.00	0.00	*680.00 F
3	1		*FRONT WINDSCREEN PILLAR LH / DD	0.00	0.00	*850.00 F
4	1		*FRONT WIPER GARNISH / CH	0.00	0.00	*120.00 F
5	1		*FRONT WIPER CORNER GARNISH LH / CH	0.00	0.00	*28.00 F
6	1		*FRONT WIPER BLADE RH / CH	0.00	0.00	*30.00 F
7	1		*FRONT WIPER BLADE LH / CH	0.00	0.00	*30.00 F
8	1		*FRONT WINDSCREEN PILLAR INNER GARNISH LH / CR4	0.00	0.00	*95.00 F
9	1		*FRONT SIDE PANEL LH / DD	0.00	0.00	*225.00 F
10	1		*FRONT PANEL / DD	0.00	0.00	*600.00 F
11	1		*FRONT HEADLAMP RH X	0.00	0.00	*225.00 F
12	1		*FRONT HEADLAMP LH / BR	0.00	0.00	*228.00 F
13	1		*FRONT HEADLAMP PANEL LH / DD	0.00	0.00	*210.00 F
14	1		*FRONT GRILLE / BR	0.00	0.00	*280.00 F
15	1		*FRONT GRILLE EMBLEM / NC	0.00	0.00	*50.00 F
16	8		*FRONT GRILLE CLIP / NC	0.00	0.00	*40.00 F
17	1		*FRONT BUMPER / BR	0.00	0.00	*280.00 F
18	1		*FRONT BUMPER SIDE BRACKET LH / MIS	0.00	0.00	*80.00 F
19	1		*FRONT BUMPER REINFORCEMENT / DD	0.00	0.00	*400.00 F
20	1		*FRONT BUMPER FOAM X	0.00	0.00	*135.00 F
21	1		*FRONT BUMPER FOGLAMP LH / MIS	0.00	0.00	*225.00 F
22	1		*FRONT BUMPER FOGLAMP COVER LH / MIS	0.00	0.00	*75.00 F
23	1		*FRONT BUMPER VERTICAL BRACKET LH / MIS	0.00	0.00	*65.00 F
24	1		*FRONT BUMPER LOWER GRILLE X	0.00	0.00	*110.00 F
25	1		*FRONT BUMPER TOW COVER X	0.00	0.00	*20.00 F
26	10		*FRONT BUMPER CLIP / NC	0.00	0.00	*20.00 F
27	1		*AIR DUCT TOP ?	0.00	0.00	*100.00 F
28	1		*AIR DUCT LOWER ?	0.00	0.00	*160.00 F
29	1		*FRONT DOOR LH / DD	0.00	0.00	*720.00 F
30	1		*FRONT DOOR HINGE TOP LH / BT	0.00	0.00	*55.00 F
31	1		*FRONT DOOR HINGE LOWER LH / BT	0.00	0.00	*55.00 F
32	1		*FRONT DOOR CHECKER LH	0.00	0.00	*40.00 F
33	1		*FRONT DOOR RUBBER LH / TAI	0.00	0.00	*80.00 F
34	1		*FRONT DOOR LOCK INNER LH / BT	0.00	0.00	*135.00 F
35	1		*FRONT DOOR GLASS LH / BR	0.00	0.00	*380.00 F
36	1		*FRONT DOOR OUTER MOULDING LH / BT	0.00	0.00	*95.00 F
37	1		*FRONT DOOR REGULATOR LH / BT	0.00	0.00	*110.00 F
38	1		*FRONT DOOR REGULATOR MOTOR LH ?	0.00	0.00	*270.00 F
39	1		*FRONT DOOR TRIMBOARD LH / CR4	0.00	0.00	*350.00 F
40	1		*FRONT DOOR HANDLE COVER INNER LH / CR4	0.00	0.00	*45.00 F
41	1		*FRONT DOOR SPEAKER LH ?	0.00	0.00	-
			CHECK PRICE			
42	1		*FRONT DOOR FAME RUBBER LH / TN	0.00	0.00	*90.00 F
43	1		*DASHBOARD ?	0.00	0.00	*700.00 F
44	1		*DASHBOARD REINFORCEMENT ?	0.00	0.00	*380.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*AIR CON BLOWER ?	0.00	0.00	*550.00 F
46	1		*HEATER UNIT ?	0.00	0.00	*1,600.00 F
47	1		*FRONT STEP GARNISH LH / BR	0.00	0.00	*65.00 F
48	1		*FRONT STEP PANEL LH / OD	0.00	0.00	*55.00 F
49	1		*FRONT WHEEL ARCH GARNISH LH / BR	0.00	0.00	*125.00 F
50	1		*CENTRE PILLAR LH X R	0.00	0.00	*800.00 F
51	1		*FRONT WHEEL RIM LH / QT	0.00	0.00	*250.00 F
52	1		*FRONT HUP CAP LH / BR	0.00	0.00	*130.00 F
53	1		*FRONT SHOCK ABSORBER LH ?	0.00	0.00	*130.00 F
54	1		*FRONT LOWER ARM LH ?	0.00	0.00	*160.00 F
55	1		*FRONT KNUCKLE ARM LH ?	0.00	0.00	*280.00 F
56	1		*FRONT KNUCKEL BEARING LH ?	0.00	0.00	*120.00 F
57	1		*FRONT STABILIZER LINK LH X	0.00	0.00	*75.00 F
58	1		*STEERING TIE ROD LH X	0.00	0.00	*85.00 F
59	1		*STEERING TIE ROD END LH X	0.00	0.00	*80.00 F

F=Franchise part

Sub Total (S\$)	14,351.00
+ Margin on L,N Items 15.00% (S\$)	2,152.65
Total Parts (S\$)	16,503.65

Kan Fook Sing Motor Workshop/GBF1716G/27/07/2020 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COMPANY ADV / <i>MC</i>	15.00
2	1	ERP STICKER / <i>MC</i>	10.00
3	1	FRONT NUMBER PLATE <i>X</i>	30.00
4	1	FRONT WINDSCREEN GUM / <i>MC</i>	40.00
Sub Total (S\$)			95.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>		New	1,600.00 <i>1200</i>
1	SPRAYPAINTING CHARGES	New	30.00 /
<u>Labour Items</u>		New	80.00 /
2	TO CHECK WIRIGN SYSTEM	New	240.00 <i>150</i>
3	TO CHECK ALIGNMENT	New	100.00 /
4	TO REMOVE/REFIT DASHBOARD	New	180.00 /
5	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	40.00 /
6	TO REMOVE/REFIT FRONT UNDERCARRIAGE LH	New	120.00 <i>80</i>
7	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	180.00 <i>120</i>
8	TO REMOVE/REFIT AND REPALCE ROOF LINING	New	2,380.00 <i>1800</i>
9	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	New	
10	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	
Gross Labour Cost (S\$)			4,950.00

Kan Fook Sing Motor Workshop/GBF1716G/27/07/2020 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
JD - Not Author
EX (PS) - \$2200
28/7/20, 1200pm
L/S
My AL My
14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: