

CC4/A1620007727/Tik93

ASS. REC. BY:

Tanglin

REF:

ALG.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD1379K Yr Regn: 2017 JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I30 c.c. 1582Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 179865 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TMAD 281 UVHJ 127 998Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 145/65/145R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at

Premier AutomotiveDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/8/20 9430, 2 days, email to Lien

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Rep. Format: _____

Lump Sum / L.B. (P) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

27-Jul-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1379 K

S/NETT

1 set n/s door sticker

\$ 100.00 ^{cut} ✓

Sundry

\$ 50.00 ^{x 11.}

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc

\$ 450.00 ^{300.}

To putty and spray painting on rear n/s door, rear n/s fender, n/s rocker panel

\$ 600.00 ⁵⁰⁰

To apply rustproofing on the repaired and replaced panels.

\$ 120.00 ^{30.}

\$ 1,320.00 ⁸³⁰

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

100
830

\$ 930 #
2 days

Tauhin 97495749
- WP

27/7/20 @ 320 pm

Repair after repair

02 days

Tauhin (Manda) was

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier (parts) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: