

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

27-Jul-20

## ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1379 K

### S/NETT

1 set	n/s door sticker	\$	100.00	ant
	Sundry	\$	50.00	x
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc	\$	450.00	300.
	To putty and spray painting on rear n/s door, rear n/s fender, n/s rocker panel	\$	600.00	500
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	30.
		\$	1,320.00	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Tanpin 97495749  
- wp'  
27/7/20 @ 320 pm  
Repair after repair  
02 days  
Tanpin 11444444

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supply of parts must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: