



CYCLE &amp; CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

CYCLE &amp; CARRIAGE



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address      |  | Owner Name & Vehicle Info |                                    |
|-----------------------------|--|---------------------------|------------------------------------|
| Pan Jian Ming               |  | Cust No/Name              | /Pan Jian Ming                     |
| 19 PUNGGO L FIELD WALK      |  | Reg No/Reg Date           | SLU9548A*FS21/ 19/12/201           |
| #05-12                      |  | Date In/Mileage           | / 0                                |
| SINGAPORE 828748            |  | Chassis No                | KNAHU815VJ7193603                  |
| Contact No Mobile: 93629364 |  | Engine No                 | D4FDHH109844                       |
|                             |  | Make/Model                | KIA/CARENS 1.7 A D EX FL DY7       |
|                             |  | Colour/Trim               | K7N GALAXY BROWN / WK SATURN BLACK |

| Account No                      | Terms | Date/Time Printed                                                                                                | CSE  | Operator      | WIP No |
|---------------------------------|-------|------------------------------------------------------------------------------------------------------------------|------|---------------|--------|
| CSM00081                        | Cash  | 27/07/2020/ 13:44                                                                                                | QUID | 247 / DonBong | 18378  |
| Description of Goods / Services |       |                                                                                                                  |      |               |        |
| E PNT88000                      |       | RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE, CUT/WELD REAR END PANEL                         |      |               |        |
| E PNT88000                      |       | TO TRANSFER REAR TAILGATE TRIM, MECHANISM AND OTHERS ATTACHMENT TO NEW PANEL                                     |      |               |        |
| E PNT88000                      |       | REMOVE AND INSTALL PARKING ASSIST                                                                                |      |               |        |
| E PNT88000                      |       | REMOVE AND INSTALL REAR CABIN AND OTHERS ATTACHMENT TO FACILITATE REPAIR WORK                                    |      |               |        |
| E PNT88000                      |       | REMOVE AND REPLACE REAR WINDSCREEN GLASS                                                                         |      |               |        |
| M SUNDRY                        |       | SUPPLY REAR WINDSCREEN SEALANT                                                                                   |      |               |        |
| M SUNDRY                        |       | SUPPLY REAR WINDSCREEN SOLAR FILM                                                                                |      |               |        |
| E PNT98000                      |       | PAINT WORK SPRAY REAR END PANEL, REAR BUMPER, REAR TAILGATE, RH REAR FENDER, LH REAR FENDER AND AFFECTED PORTION |      |               |        |
| M SUNDRY                        |       | APPLY BODY SEALANT                                                                                               |      |               |        |
| A 54900099                      |       | CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM                                                                       |      |               |        |
| M SUNDRY                        |       | PERFORM RUST PREVENTION                                                                                          |      |               |        |
| A 10028901                      |       | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST                                      |      |               |        |
| M SUNDRY                        |       | SUPPLY C&C LOGO                                                                                                  |      |               |        |
| M SUNDRY                        |       | SUPPLY REAR NUMBER PLATE WITH FRAME                                                                              |      |               |        |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address      |  | Owner Name & Vehicle Info |                                    |
|-----------------------------|--|---------------------------|------------------------------------|
| Pan Jian Ming               |  | Cust No/Name              | /Pan Jian Ming                     |
| 19 PUNGGOL FIELD WALK       |  | Reg No/Reg Date           | SLU9548A*FS21/ 19/12/201           |
| #05-12                      |  | Date In/Mileage           | / 0                                |
| SINGAPORE 828748            |  | Chassis No                | KNAHU815VJ7193603                  |
| Contact No Mobile: 93629364 |  | Engine No                 | D4FDHH109844                       |
|                             |  | Make/Model                | KIA/CARENS 1.7 A D EX FL DY7       |
|                             |  | Colour/Trim               | K7N GALAXY BROWN / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator      | WIP No |
|------------|-------|-------------------|-----|---------------|--------|
| CSM00081   | Cash  | 27/07/2020/ 13:44 | QUD | 247 / DonBong | 18378  |

| Description of Goods / Services   |             |  |  |  | Qty  | Unit Price | Disc% | Amount   |
|-----------------------------------|-------------|--|--|--|------|------------|-------|----------|
| M SUNDRY                          |             |  |  |  |      |            |       | 30 50.00 |
| SUNDRIES                          |             |  |  |  |      |            |       |          |
| M PANEL ASSY-TAIL GATE            | bt          |  |  |  | 1.00 | 1218.00    | 00.00 | 1218.00  |
| M GARNISH-TAIL GATE,UPR           |             |  |  |  | 1.00 | 135.00     | 00.00 | 135.00   |
| M MOULDING-CR PIECE               | X su        |  |  |  | 1.00 | 104.00     | 00.00 | 104.00   |
| M ORNAMENT-KIA nee                |             |  |  |  | 1.00 | 76.00      | 00.00 | 76.00    |
| M EMBLEM-CARENS nee               |             |  |  |  | 1.00 | 36.00      | 00.00 | 36.00    |
| M EMBLEM-CRDI nee                 |             |  |  |  | 1.00 | 29.00      | 00.00 | 29.00    |
| M CROSSMEMBER ASSY-RR END         | ? xsu       |  |  |  | 1.00 | 453.00     | 00.00 | 453.00   |
| M GLASS ASSY-TAIL GATE            | ? photo xsu |  |  |  | 1.00 | 490.00     | 00.00 | 490.00   |
| M STOPPER-RR WINDOW GLASS         | nee         |  |  |  | 2.00 | 15.00      | 00.00 | 30.00    |
| M PAD-WINDSHIELD GLASS            | nee         |  |  |  | 5.00 | 2.00       | 00.00 | 10.00    |
| M GROMMET-REAR WIPER              | ? xsu       |  |  |  | 1.00 | 5.00       | 00.00 | 5.00     |
| M TRIM-TRANSVERSE RR              | ? xsu       |  |  |  | 1.00 | 71.00      | 00.00 | 71.00    |
| M BRACKET ASSY-RR BUMPER SIDE, LH | ? xsu       |  |  |  | 1.00 | 25.00      | 00.00 | 25.00    |
| M BRACKET ASSY-RR BUMPER SIDE, RH | ? xsu       |  |  |  | 1.00 | 25.00      | 00.00 | 25.00    |
| M STAY-RR BUMPER LH               | ? xsu       |  |  |  | 1.00 | 159.00     | 00.00 | 159.00   |
| M STAY-RR BUMPER RH               | ? xsu       |  |  |  | 1.00 | 159.00     | 00.00 | 159.00   |
| M ANTENNA ASSY-SMARTKEY           | ? xsu       |  |  |  | 1.00 | 79.00      | 00.00 | 79.00    |
| M BEAM-RR BUMPER                  | ? can       |  |  |  | 1.00 | 367.00     | 00.00 | 367.00   |
| M BRACKET-RR BUMPER RAIL, UPR     | ? xsu       |  |  |  | 2.00 | 5.00       | 00.00 | 10.00    |
| M BRACKET-RR BUMPER RAIL, LWR     | ? xsu       |  |  |  | 2.00 | 5.00       | 00.00 | 10.00    |
| M BRACKET-RR BUMPER LWR, CTR      | ? xsu       |  |  |  | 1.00 | 5.00       | 00.00 | 5.00     |
| M BRACKET-RR BUMPER RAIL, LWR     | ? xsu       |  |  |  | 2.00 | 5.00       | 00.00 | 10.00    |
| M WIRING HARNESS-R.P.A.S          | ? xsu       |  |  |  | 1.00 | 251.00     | 00.00 | 251.00   |
| M RETAINER                        | ? xsu       |  |  |  | 8.00 | 1.00       | 00.00 | 8.00     |
| M BRACKET-FR BUMPER SIDE, RH      | ? xsu       |  |  |  | 1.00 | 4.00       | 00.00 | 4.00     |
| M BRACKET-FR BUMPER SIDE, LH      | ? xsu       |  |  |  | 1.00 | 4.00       | 00.00 | 4.00     |
| M COVER-RR BUMPER, UPR            | de          |  |  |  | 1.00 | 576.00     | 00.00 | 576.00   |
| M COVER-RR BUMPER LWR             | de          |  |  |  | 1.00 | 211.00     | 00.00 | 211.00   |
| M LAMP ASSY-REAR FOG, RH          | ? xsu       |  |  |  | 1.00 | 116.00     | 00.00 | 116.00   |
| M LAMP ASSY-REAR FOG, LH          | ? xsu       |  |  |  | 1.00 | 116.00     | 00.00 | 116.00   |
| M HOLDER-BACK WARING SYSTEM OTR   | ? xsu       |  |  |  | 2.00 | 4.00       | 00.00 | 8.00     |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windshield in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windshield.





CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address      |  | Owner Name & Vehicle Info |                                    |
|-----------------------------|--|---------------------------|------------------------------------|
| Pan Jian Ming               |  | Cust No/Name              | /Pan Jian Ming                     |
| 19 PUNGOL FIELD WALK        |  | Reg No/Reg Date           | SLU9548A*FS21/ 19/12/201           |
| #05-12                      |  | Date In/Mileage           | / 0                                |
| SINGAPORE 828748            |  | Chassis No                | KNAHU815VJ7193603                  |
| Contact No Mobile: 93629364 |  | Engine No                 | D4FDHH109844                       |
|                             |  | Make/Model                | KIA/CARENS 1.7 A D EX FL DY7       |
|                             |  | Colour/Trim               | K7N GALAXY BROWN / WK SATURN BLACK |

| Account No                      | Terms                          | Date/Time Printed | CSE  | Operator      | WIP No |
|---------------------------------|--------------------------------|-------------------|------|---------------|--------|
| CSM00081                        | Cash                           | 27/07/2020/ 13:44 | QUD  | 247 / DonBong | 18378  |
| Description of Goods / Services |                                |                   |      |               |        |
| M                               | HOLDER-BACK WARING SYSTEM      | INR               | 2.00 | 4.00          | 00.00  |
| M                               | ULTRASONIC SENSOR ASSY-P.A.S   | 7                 | 1.00 | 162.00        | 00.00  |
| M                               | ULTRASONIC SENSOR ASSY-P.A.S   | 7                 | 1.00 | 162.00        | 00.00  |
| M                               | ULTRASONIC SENSOR ASSY-P.A.S   | 7                 | 1.00 | 162.00        | 00.00  |
| M                               | ULTRASONIC SENSOR ASSY-P.A.S   | 7                 | 1.00 | 162.00        | 00.00  |
| M                               | LAMP ASSY-REAR COMB INSIDE, LH | 2                 | 1.00 | 213.00        | 00.00  |
| M                               | LAMP ASSY-REAR COMB INSIDE, RH | 2                 | 1.00 | 213.00        | 00.00  |
| M                               | LAMP ASSY-REAR COMBINATION, LH | 2                 | 1.00 | 213.00        | 00.00  |
| M                               | LAMP ASSY-REAR COMBINATION, RH | 2                 | 1.00 | 357.00        | 00.00  |
|                                 |                                |                   | 1.00 | 357.00        | 00.00  |

# Estimate

SURVEYOR NAME: Rasul-4p 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 06/08/2020 @

REMARKS: 6 days

Repairing so far paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirmation is accepted by is allowed  
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

14,197.00

|           |          |               |           |
|-----------|----------|---------------|-----------|
| 7% GST on | 13788.00 | Nett          | 13,788.00 |
|           |          |               | 965.16    |
|           |          | Total Payable | 14,753.16 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.