



Exceptional Journeys

Surveyor : RASUL LKK
Claim : TP CHINA TAIPING
DOA : 25.07.2020
Emailed : 01.09.2020, 6pm
Date survey : 06.08.2020

VEHICLE NO : SLU 9548 A
MODEL : KIA CARENS 1.7 A D EX
WIP : 18378

Material	:	\$	2,762.00
Labour	:	\$	4,510.00
Sub-Total	:	\$	7,272.00
	:		-
Less Excess	:	\$	-
Total	:	\$	7,272.00
GST 7%	:	\$	509.04
Grand Total	:	\$	7,781.04
Finalise By/Date	:	LOI / 01/09/2020	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 6 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 8

☒ TP claim GZ6707K

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Pan Jian Ming 19 PUNGGOL FIELD WALK #05-12 SINGAPORE 828748 Contact No *Mobile: 93629364 20/08/2020	Cust No/Name	/Pan Jian Ming
	Reg No/Reg Date	SLU9548A / 19/12/2017
	Date In/Mileage	20/08/2020/ 45378
	Chassis/Package	KNAHU815VJ7193603 /KC17P
	Engine No	D4FDHH109844
	Make/Model	KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim	K7N GALAXY BROWN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	01/09/2020/ 16:14	TLD	260 / AiTing	18378			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR TAILGATE, REAR BUMPER, REPAIR REAR END PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1650.00
E PNT88000 TRANSFER REAR TAILGATE TRIMS, MECHANISMS, AND ALL OTHER ATTACHMENTS TO TO NEW PANEL								✓ 250.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST TO FACILITATE REPAIR								✓ 80.00
E PNT88000 REMOVE AND INSTALL REAR CABIN AND OTHER ATTACHMENTS TO FACILITATE REPAIR								✓ 250.00
E PNT88000 REMOVE AND INSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST								✓ 300.00
M SUNDRY SUPPLY REAR WINDSCREEN GLASS SEALANT								✓ 80.00
E PNT98000 RESPRAY ON REAR END PANEL, REAR BUMPER, REAR TAILGATE, AND ALL OTHER AFFECTED PORTIONS TO THE SAME								✓ 1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓ 30.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 120.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 200.00
M SUNDRY SUPPLY C&C LOGO								✓ 50.00
M SUNDRY SUNDRIES								✓ 30.00
E PNT98000 RESPRAY ON SKID PLATE-RR BUMPER								210.00
X PANEL ASSY-TAIL GATE					1.00	✓ 1218.00	00.00	1218.00
X ORNAMENT-KIA					1.00	✓ 76.00	00.00	76.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Pan Jian Ming	Cust No/Name /Pan Jian Ming
19 PUNGGOL FIELD WALK	Reg No/Reg Date SLU9548A / 19/12/2017
#05-12	Date In/Mileage 20/08/2020/ 45378
SINGAPORE 828748	Chassis/Package KNAHU815VJ7193603 /KC17P
Contact No *Mobile: 93629364	Engine No D4FDHH109844
20/08/2020	Make/Model KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim K7N GALAXY BROWN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	01/09/2020/ 16:14	TLD	260 / AiTing	18378
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X EMBLEM-CARENS		1.00	✓ 36.00	00.00	36.00
X EMBLEM-CRDI		1.00	✓ 29.00	00.00	29.00
X STOPPER-RR WINDOW GLASS		2.00	✓ 15.00	00.00	30.00
X PAD-WINDSHIELD GLASS		6.00	✓ 2.00	00.00	12.00
X BEAM-RR BUMPER		1.00	? 367.00	00.00	367.00
X COVER-RR BUMPER,UPR		1.00	✓ 576.00	00.00	576.00
X COVER-RR BUMPER LWR		1.00	✓ 211.00	00.00	211.00
X HOLDER-BACK WARING SYSTEM INR		2.00	✓ 4.00	00.00	8.00
X SKID PLATE-RR BUMPER		1.00	179.00	00.00	179.00
X CLIP		10.00	2.00	00.00	20.00
Z TEXT					
TP CLAIM CHINA TAIPING GZ6707K					
DOA : 25.07.20					
SURVEYOR RASUL LKK 06.08.20					
REPAIR 06 DAYS					
Guarantee Your Warranty, Maintain with Cycle & Carriage!					

Parts	2,762.00	Nett	7,272.00
Labour	4,230.00	7% GST on	509.04
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	7,781.04
Sundry/Others	280.00		
Total(w/o GST)	7,272.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

INSURANCE CO. : **CHINA TAIPING**

Supplementary Parts For Registration No.: **SLU 9548 A**

Materials

Cost (\$)

1	Skid plate-RR bumper	179.00
2	Clip (x10)	20.00
Total		199.00
Total Materials		199.00

Labour

Cost (\$)

1	Respray on skid plate-RR bumper	210.00
Total Labour		210.00
Taxable amount		409.00
7% GST		28.63
Grand total		<u>\$ 437.63</u>

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6565 1240 / 6567 5258