

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007738/BGA3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800155622	
Claimant Vehicle No :	GW7289J	Insured Vehicle No :	SMG6882R	
Date of Loss:	24/07/2020	Nature of Claim:	TP	Claim No: 9438508175SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW7289J		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2737996
Reg. Date:	13/09/2017 (Man. Year: 2017)	Chassis No:	JTFAT35Y00K208712
Colour:	Blue	Odometer:	218954 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 /15	Rear Tyre Size:	155/12
Front Left Side:	Michelin 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,718.32	1,516.15	7,202.17	82.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	850.00	3,130.00	78.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,698.32	2,366.15	10,332.17	81.37
Approved Total (Overridden) (S\$)		1,850.00		

(S\$)	12,698.32	1,850.00	10,848.32	85.43
+ GST 7.00/7.00% (S\$)	888.88	129.50	759.38	85.43
Nett Amount (S\$)	13,587.20	1,979.50	11,607.70	85.43
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,686.95		

INSPECTION

Date of Assignment: 27/07/2020

Date Inspected: 27/07/2020

Estimated Period of Repair: 4.0 days

Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE	Not Damaged	1,535.00 FL	*- FL
2	1		*REAR GATE STICKER DYNA	Necessary	110.90 FL	*68.50 FL
3	1		*REAR GATE STICKER TOYOTA	Necessary	145.00 FL	*145.00 FL
4	4		*REAR GATE HINGES	Not Applicable	274.00 FL	*- FL
5	1		*REAR GATE LATCH LOCK	O/S Bent	217.20 FL	*108.60 FL
6	2		*REAR GATE SIDE LOCK LEVER	Not Damaged	139.20 FL	*- FL
7	2		*REAR GATE STOPPER BRACKET	Bent	373.40 FL	*219.40 FL
8	2		*REAR GATE REFLECTOR	Not Damaged	57.00 FL	*- FL
9	1		*REAR END PANEL	Not Damaged	683.20 FL	*- FL
10	1		*REAR SIDE END PANEL	Dented	585.00 FL	*449.00 FL
11	1		*REAR NO PLATE BRACKET	Bent	145.50 FL	*145.50 FL
12	2		*REAR NO PLATE LAMP	Not Damaged	129.00 FL	*- FL
13	1		*REAR STEP BRACKET	Not Necessary	75.30 FL	*- FL
14	1		*TAILLAMP	O/S Cut	571.80 FL	*285.90 FL
15	2		*TAILLAMP PANEL	Not Damaged	397.20 FL	*- FL
16	1		*SPARE TYRE CHAIN BLOCK	Bent	397.00 FL	*386.30 FL
17	1		*REAR FLOOR BED	Not Damaged	3,885.00 FL	*- FL
18	1		*EXHAUST PIPE	Repair	895.60 FL	*- FL
19	1		*EXHAUST PIPE MUNTING	Not Damaged	114.80 FL	*- FL
20	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
21	1		*REAR GATE STICKER 70KM/H	Necessary	30.00 FS	*10.00 FS
22	1		*REAR GATE STICKER FLAMMABLE GAS	Necessary	80.00 FS	*50.00 FS
23	1		*REAR GATE STICKER DANGER HIGHLY FLAMMABLE	Necessary	180.00 FS	*80.00 FS
24	1		*REAR NO PLATE	Bent	80.00 FS	*20.00 FS
25	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
26	1		*REAR SIDE END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,401.10	1,968.20
- List Item Discount on L Items 25.00/25.00% (\$)	2,682.78	452.05
Total Parts (\$)	8,718.32	1,516.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REAR GATE	New	200.00	0.00
2	R&R EXHAUST PIPE	New	180.00	50.00
3	R&R UPHOLSTERY	New	200.00	0.00
4	PANEL BEAT	New	1,600.00	400.00
5	RUST PROOFING	New	200.00	0.00
6	SPRAY PAINTING	New	1,600.00	400.00
Gross Labour Cost (\$)			3,980.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >