

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3289J

| Qty | Description of Parts   | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS   |                         |                               |                   |
| 1   | L/R SLIDING DOOR (WCP) (CONSISTENT)  | BENT                    | 650.00                        | 650.00            |
| 1   | L/SIDE WDW SEAL KIT (WCP) (CONSISTENT) (NPA)                                       | NOT NECESSARY           | -                             | -                 |
| 1   | L/R LOCK STRIKER (WCP) (CONSISTENT)  | TO REPAIR SEE<br>LABOUR | 35.00                         | -                 |
| 1   | L/R DOOR LOCK (WCP) (CONSISTENT)   | NOT NECESSARY           | 120.00                        | -                 |
| 1   | L/R DOOR TRIM (WCP) (CONSISTENT)   | NOT NECESSARY           | 200.00                        | -                 |
| 1   | L/SIDE PANEL (WCP) (CONSISTENT)  | BENT                    | 460.00                        | 460.00            |
| 1   | L/LOWER ROLLER ARM (WCP) (CONSISTENT)  | NOT NECESSARY           | 130.00                        | -                 |
| 1   | L/S WINDOW BOND KIT (WCP) (CONSISTENT) (NPA)                                       | NOT NECESSARY           | -                             | -                 |
| 1   | L/R WDW BONDING KIT (WCP) (CONSISTENT) (NPA)                                       | NOT NECESSARY           | -                             | -                 |
|     | COST PLUS 15%  |                         | 239.25                        | 166.50            |
|     |  |                         | 1,834.25                      | 1,276.50          |
|     | SPECIAL NETT ITEMS   |                         |                               |                   |
| 1   | 'PRIVATE' STICKER (SN)(CONSISTENT)   | NECESSARY               | 15.00                         | 15.00             |
| 1   | COMPANY STICKER STICKER (SN)(CONSISTENT)   | NECESSARY               | 180.00                        | 180.00            |
| 1   | SEALANT SLIDING DOOR WS (SN)(CONSISTENT)   | NECESSARY               | 40.00                         | 40.00             |
| 1   | DAMP SEAL SLIDING DOOR LH (SN)(CONSISTENT)   | NECESSARY               | 20.00                         | 20.00             |
| 1   | LH GLASS SEALANT LH EXTENSION (SN)(CONSISTENT)                                     | NECESSARY               | 40.00                         | 40.00             |
| 1   | WS DAMP SEAL LH EXTENSION (SN)(CONSISTENT)   | NECESSARY               | 20.00                         | 20.00             |
| 1   | SEALANT RR LH PANEL WS (SN)(CONSISTENT)  | NECESSARY               | 60.00                         | 60.00             |
| 1   | DAMP SEAL RR LH PANEL WS (SN)(CONSISTENT)  | NECESSARY               | 20.00                         | 20.00             |
|     |  |                         | 395.00                        | 395.00            |
|     | <u>LABOUR</u>  |                         |                               |                   |
|     | SEATS REMOVE & REFIT .   |                         | 180.00                        | 120.00            |
|     | 81.0 WU X 45.00 SGD/H.   |                         | 364.50                        | 355.50            |
|     | LABOUR COST 88.0 WU X 45.00 SGD/H.INCLUSIVE OF<br>THE REPAIR OF L/R LOCK STRIKER . |                         | 396.00                        | 396.00            |
|     | MATERIAL COST.   |                         | 148.25                        | 148.25            |
|     |  |                         | 1,088.75                      | 1,019.75          |
|     | GRAND TOTAL  |                         | 3,318.00                      | 2,691.25          |

Report Ref No. CC4/ASM20007739/Kea3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 2,250.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  | ·        |

Report Ref No. CC4/ASM20007739/Kea3q2

**KONG SENG CHEONG** 

**Licensed Appraiser**