



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0220616

Date of Report : 16/07/2016

To : Mr Khairudin Bin Jantan
C/o. 1 Kaki Bukit Ave 6
#01-72/73 Autobay
Singapore 417883

Date of Assignment : 17/06/2016
Report requested by : Mr Khairudin Bin Jantan
Date of Accident : 15/06/2016
Date of Inspection : 17/06/2016
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SGP4001D
Make & Model : Toyota Picnic (A)
Year of Registration : 2006
Colour : Met. Silver

Engine Capacity (cc) : 1998cc
Mileage (km) : 283883km
Chassis / Frame No. : JTEGH23B300022652
Engine No. : 1AZ5498687

TYRE CONDITION

Front LH : 4 mm	Front RH : 4 mm
Make : Yokohama	Make : Yokohama
Rear LH : 4 mm	Rear RH : 4 mm
Make : Yokohama	Make : Yokohama

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF INSPECTION

Location : M/s. Hanip Automobiles Pte Ltd
1, Kaki Bukit Ave 6, #01-72/73, Autobay @ Kaki Bukit, Singapore 417883

ASSESSMENT

Repairer's Estimate : \$ 15,082.70
Revised Amount : \$ 11,392.45
Less Excess : \$ -
Recommended Reserve : \$ 9,650.00 (Lump Sum)

Estimated Normal Period of Repairs : 12 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SGP4001D

Report No. : PAS/TP/0220616

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Hanip Automobiles Pte Ltd, 1, Kaki Bukit Ave 6, #01-72/73, Autobay @ Kaki Bukit, Singapore 417883.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, LH taillamp, LH reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$11,392.45.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,650.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SGP4001D

Report No. : PAS/TP/0220616

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Tailgate	Dented		\$ 1,506.40	\$ 1,506.40
2	1 pc	Tailgate emblem (Logo)	Necessary		\$ 79.30	\$ 79.30
3	1 pc	Tailgate emblem (Picnic)	Necessary		\$ 64.80	\$ 64.80
4	1 pc	Tailgate emblem (Toyota)	Necessary		\$ 48.30	\$ 48.30
5	1 pc	Tailgate emblem (Deluxe)	Necessary		\$ 46.10	\$ 46.10
6	1 pc	Tailgate no.plate garnish	Refit		\$ 265.70	\$ -
7	2 pcs	Tailgate no.plate lamp R/L	Refit	\$ 54.70	\$ 109.40	\$ -
8	2 pcs	Tailgate lift support R/L	Refit	\$ 214.60	\$ 429.20	\$ -
9	2 pcs	Tailgate reflector lamp R/L	LH Cracked	\$ 230.50	\$ 461.00	\$ 230.50
10	1 pc	Tailgate inner trim	Dented/Deformed		\$ 384.10	\$ 384.10
11	1 pc	Rr windscreen moulding	Necessary		\$ 133.60	\$ 133.60
12	1 pc	Rr windscreen moulding dam kit	Necessary		\$ 87.50	\$ 87.50
13	1 pc	Rr windscreen wiper motor	Refit		\$ 765.40	\$ -
14	1 pc	Rr windscreen wiper arm	Refit		\$ 65.70	\$ -
15	1 pc	Tailgate lock	Dented/Jammed		\$ 286.20	\$ 286.20
16	1 pc	Tailgate lock striker	Bent		\$ 41.20	\$ 41.20
17	1 pc	Tailgate weatherstrip	Torn/Necessary		\$ 354.40	\$ 354.40
18	2 pcs	Taillamp R/L	LH Cracked	\$ 357.30	\$ 714.60	\$ 357.30
19	2 pcs	Taillamp panel R/L	Dented/Repair	\$ 142.50	\$ 285.00	\$ -
20	1 pc	Rr bumper	Dented		\$ 564.10	\$ 564.10
21	2 pcs	Rr bumper tow cover R/L	LH Missing	\$ 30.20	\$ 60.40	\$ 30.20
22	6 pcs	Rr bumper clip	Necessary	\$ 4.20	\$ 25.20	\$ 25.20
23	2 pcs	Rr bumper retainer R/L	Necessary	\$ 51.20	\$ 102.40	\$ 102.40
24	2 pcs	Rr bumper side support R/L	Necessary	\$ 38.40	\$ 76.80	\$ 76.80
25	2 pcs	Rr bumper seal R/L	Refit	\$ 76.80	\$ 153.60	\$ -
26	2 pcs	Rr bumper reflector R/L	LH Cracked	\$ 63.90	\$ 127.80	\$ 63.90
27	1 pc	Rr end panel	Dented		\$ 440.50	\$ 440.50
28	1 pc	Rr end panel garnish	Dented/Deformed		\$ 401.80	\$ 401.80
29	2 pcs	Rr fender inner trim R/L	Dented/Deformed	\$ 833.80	\$ 1,667.60	\$ 1,667.60
30	1 pc	Rr compartment cover	Dented/Deformed		\$ 800.40	\$ 800.40
31	1 pc	Rr floor panel	Dented		\$ 804.30	\$ 804.30
32	1 pc	Rr floor panel lining	Torn/Deformed		\$ 437.10	\$ 437.10
33	1 pc	Rr floor panel reinforcement	Bent/Necessary		\$ 110.50	\$ 110.50
34	1 pc	Rr floor panel bracket	Necessary		\$ 72.10	\$ 72.10
35	1 pc	Exhaust silencer	Refit		\$ 1,031.10	\$ -
					\$ 13,003.60	\$ 9,216.60
Less Discount : 25%					\$ 3,250.90	25% \$ 2,304.15
List Parts Sub-Total :					\$ 9,752.70	\$ 6,912.45
1	1 pc	Rr windscreen sealant	Necessary	S/N	\$ 50.00	\$ 40.00
2	1 set	Rr no.plate (w/bracket)	Dented/Cracked	S/N	\$ 50.00	\$ 50.00
3	1 set	Rr reverse sensor (4pcs type)	Dented/Damaged	S/N	\$ 400.00	\$ 350.00
4	1 pc	Rr end panel sealant	Necessary	S/N	\$ 50.00	\$ 40.00
5	1 pc	Rr floor panel sealant	Necessary	S/N	\$ 50.00	\$ 40.00
Special Nett Sub-Total :					\$ 600.00	\$ 520.00
Parts Total :					\$ 10,352.70	\$ 7,432.45



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No. : SGP4001D

Report No. : PAS/TP/0220616

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 80.00	\$ 50.00
2	To transfer rear windscreen to new tailgate.	\$ 150.00	\$ 120.00
3	To transfer tailgate component parts to new tailgate.	\$ 120.00	\$ 100.00
4	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	\$ 250.00	\$ 220.00
5	To remove and reinstall exhaust silencer for necessary.	\$ 150.00	\$ 120.00
6	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 80.00	\$ 60.00
7	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,800.00	\$ 1,540.00
8	To conduct chassis alignments.	\$ 400.00	\$ 300.00
9	To spray painting on affected area.	\$ 1,500.00	\$ 1,300.00
10	To spray anti-rust coating on new and affected panels.	\$ 200.00	\$ 150.00
Labour Total :		\$ 4,730.00	\$ 3,960.00
Total (Parts & Labour) :		\$ 15,082.70	\$ 11,392.45

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,650.00

Under normal circumstances, the repairs should be completed within a reasonable period of **12 Working Days**.

82 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.





















