



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/LAW20007740/Atf3e2

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-08-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SHC 3355X	Veh. Inspected	SGP 4001D
Policy No.		Coverage (\$)	0.00
Claim No.	MCT/16060653	Excess (\$)	0.00
Assign From	CHEN MEIJUAN	Assign Date	15/07/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PICNIC	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JTEGH23B300022652	Colour	SILVER
Odometer	421376	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	MICHELIN	6 mm
L/H Front Tyre	205/60 R16	MICHELIN	6 mm
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	15/06/2016	Inspection Date	28/07/2020
Survey held at	BLK 223A JURONG EAST ST 21 S'PORE 601223		
Repairer	HANIP AUTOMOBILES ENGINEERING		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------