

Text size + -

**Enquire Vehicle & Owner Information ( Vehicle No. GX1486R As At 15 Jun 2016 / 11:45:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: HANIP

**Current Owner Details**

Owner ID Type: Business

Owner ID: 53225639E

Owner Name: ANBAO MOTOR SERVICES

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 48

Registered Street Name: TOH GUAN ROAD EAST

Registered Unit No.: # 03 - 130

Registered Building Name: ENTERPRISE HUB

Registered Postal Code: 608586

**Current Vehicle Details**

Vehicle No.: GX1486R

Make Description/Model: MITSUBISHI / L300 HR M

Insurance Company Name: EQ INSURANCE COMPANY LTD

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)



redefining insurance

AXA Insurance Singapore Pte Ltd  
 ☎ 1800 580 4888 (Within Singapore)  
 (65) 6880 4888 (International)  
 📠 (65) 6880 4740  
 ✉ customer.care@axa.com.sg  
 🌐 www.axa.com.sg

## Certificate of Insurance

account number  
00612

As a vehicle (Third-Party Risks and Compensation Act, (Chapter 189) - Motor Vehicle) (Third-Party Risks and Compensation Rules, 1987) Road Transport Act, 1987 (Malaysia)  
 Motor Vehicle (Third-Party Risks) Rules, 1988 (Malaysia)

### Policy details

|                             |  |                    |                   |
|-----------------------------|--|--------------------|-------------------|
| Policyholder name           | KHAIRUDIN JANTAR                                     | Certificate number | GA078636 / 1      |
| Cover                       | Comprehensive  | Chassis number     | ITEGH238300022652 |
| Plan name                   | Private MPV APW                                      | Engine number      | 1A25498687        |
| NCD applicable              | 50%  |                    |                   |
| Vehicle registration number | SGF4001D   |                    |                   |
| Period of insurance         | from 14/12/2015 to 13/12/2016 (both dates inclusive) |                    |                   |
| Finance loan company        | DBS BANK LTD   |                    |                   |

### Persons or classes of persons entitled to drive\*

- (a) The Policyholder  
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace making or such similar purposes.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

|        |                         |            |
|--------|-------------------------|------------|
| EXCESS | Basic Own Damage Excess | SGD 0.00   |
|        | Windscreen Excess       | SGD 100.00 |

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorized Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Van shops.

### Additional clauses & endorsements to your policy

Nil

(We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Singapore Pte Ltd

Authorized signature

### Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender this Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration in this effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Financial Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, covered, contingent, co-insurance, etc.

AXA Insurance Singapore Pte Ltd (M2-0009922-2)  
 8 Shenon Way, #27-01, AXA Tower,  
 Singapore 068811  
 Customer Care Department, #B1-01

1 of 3



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St. 3 #02-24 S(529890)

Mobile 8295 2204 Fax 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

## INVOICE

Mr Khairudin Bin Jantan  
C/o. 1 Kaki Bukit Ave 6  
#01-72/73 Autobay  
Singapore 417883

Invoice No. : HA/1607-24

Date : 16/07/2016

| Descriptions  | Amount (SGD)           |
|---|------------------------|
| <b>Services rendered for appraiser / inspection report :-</b> |                        |
| Survey Fee  |                        |
| Photographs   |                        |
| Transport Fees  |                        |
| Re-inspection Fees  |                        |
| <b>Total :</b>  | <b>SGD : \$ 602.00</b> |
| SGD Dollar : Six Hundred Two Dollars Only.                    |                        |
| Our Reference : PAS/TP/0220616                                |                        |
| Vehicle No. : SGP4001D  |                        |
| Make & Model : Toyota Picnic (A)                              |                        |
| Your Claim No. : Third Party Claim                            |                        |

### Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 0722 8508 Email: pasvos@hotmail.com

Business Reg: 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0220616

Date of Report : 16/07/2016

To : Mr Khairudin Bin Jantan  
C/o. 1 Kaki Bukit Ave 6  
#01-72/73 Autobay  
Singapore 417883

Date of Assignment : 17/06/2016  
Report requested by : Mr Khairudin Bin Jantan  
Date of Accident : 15/06/2016  
Date of Inspection : 17/06/2016  
Claim No. : Third Party Claim  
Policy No. : -

## PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SGP4001D  
Make & Model : Toyota Picnic (A)  
Year of Registration : 2006  
Colour : Met. Silver

Engine Capacity (cc) : 1998cc  
Mileage (km) : 283883km  
Chassis / Frame No. : JTEGH23B300022652  
Engine No. : 1AZ5498687

## TYRE CONDITION

Front LH : 4 mm  
Make : Yokohama

Front RH : 4 mm  
Make : Yokohama

Rear LH : 4 mm  
Make : Yokohama

Rear RH : 4 mm  
Make : Yokohama

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

## PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

## PLACE OF INSPECTION

Location : M/s. Hanip Automobiles Pte Ltd  
1, Kaki Bukit Ave 6, #01-72/73, Autobay @ Kaki Bukit, Singapore 417883

## ASSESSMENT

Repairer's Estimate : \$ 15,082.70  
Revised Amount : \$ 11,392.45  
Less Excess : \$ -  
Recommended Reserve : \$ 9,650.00 (Lump Sum)

Estimated Normal Period of Repairs : 12 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : SGP4001D

Report No. : PAS/TP/0220616

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Hanip Automobiles Pte Ltd, 1, Kaki Bukit Ave 6, #01-72/73, Autobay @ Kaki Bukit, Singapore 417883.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the rear portion.

### DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, LH taillamp, LH reflectors, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$11,392.45.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,650.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
Prominent Appraiser Services Pte Ltd

  
Andrew How  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No. : SGP4001D

Report No. : PAS/TP/0220616

## APPRAISEMENT SCHEDULE

| S/No. | Qty   | Parts Descriptions             | Condition       |           | Repairer's Estimate (\$\$) | Our Assessment (\$\$) |
|-------|-------|--------------------------------|-----------------|-----------|----------------------------|-----------------------|
| 1     | 1 pc  | Tailgate                       | Dented          |           | \$ 1,506.40                | \$ 1,506.40           |
| 2     | 1 pc  | Tailgate emblem (Logo)         | Necessary       |           | \$ 79.30                   | \$ 79.30              |
| 3     | 1 pc  | Tailgate emblem (Picnic)       | Necessary       |           | \$ 64.80                   | \$ 64.80              |
| 4     | 1 pc  | Tailgate emblem (Toyota)       | Necessary       |           | \$ 48.30                   | \$ 48.30              |
| 5     | 1 pc  | Tailgate emblem (Deluxe)       | Necessary       |           | \$ 46.10                   | \$ 46.10              |
| 6     | 1 pc  | Tailgate no.plate garnish      | Refit           |           | \$ 265.70                  | \$ -                  |
| 7     | 2 pcs | Tailgate no.plate lamp R/L     | Refit           | \$ 54.70  | \$ 109.40                  | \$ -                  |
| 8     | 2 pcs | Tailgate lift support R/L      | Refit           | \$ 214.60 | \$ 429.20                  | \$ -                  |
| 9     | 2 pcs | Tailgate reflector lamp R/L    | LH Cracked      | \$ 230.50 | \$ 461.00                  | \$ 230.50             |
| 10    | 1 pc  | Tailgate inner trim            | Dented/Deformed |           | \$ 384.10                  | \$ 384.10             |
| 11    | 1 pc  | Rr windscreen moulding         | Necessary       |           | \$ 133.60                  | \$ 133.60             |
| 12    | 1 pc  | Rr windscreen moulding dam kit | Necessary       |           | \$ 87.50                   | \$ 87.50              |
| 13    | 1 pc  | Rr windscreen wiper motor      | Refit           |           | \$ 765.40                  | \$ -                  |
| 14    | 1 pc  | Rr windscreen wiper arm        | Refit           |           | \$ 65.70                   | \$ -                  |
| 15    | 1 pc  | Tailgate lock                  | Dented/Jammed   |           | \$ 286.20                  | \$ 286.20             |
| 16    | 1 pc  | Tailgate lock striker          | Bent            |           | \$ 41.20                   | \$ 41.20              |
| 17    | 1 pc  | Tailgate weatherstrip          | Torn/Necessary  |           | \$ 354.40                  | \$ 354.40             |
| 18    | 2 pcs | Taillamp R/L                   | LH Cracked      | \$ 357.30 | \$ 714.60                  | \$ 357.30             |
| 19    | 2 pcs | Taillamp panel R/L             | Dented/Repair   | \$ 142.50 | \$ 285.00                  | \$ -                  |
| 20    | 1 pc  | Rr bumper                      | Dented          |           | \$ 564.10                  | \$ 564.10             |
| 21    | 2 pcs | Rr bumper tow cover R/L        | LH Missing      | \$ 30.20  | \$ 60.40                   | \$ 30.20              |
| 22    | 6 pcs | Rr bumper clip                 | Necessary       | \$ 4.20   | \$ 25.20                   | \$ 25.20              |
| 23    | 2 pcs | Rr bumper retainer R/L         | Necessary       | \$ 51.20  | \$ 102.40                  | \$ 102.40             |
| 24    | 2 pcs | Rr bumper side support R/L     | Necessary       | \$ 38.40  | \$ 76.80                   | \$ 76.80              |
| 25    | 2 pcs | Rr bumper seal R/L             | Refit           | \$ 76.80  | \$ 153.60                  | \$ -                  |
| 26    | 2 pcs | Rr bumper reflector R/L        | LH Cracked      | \$ 63.90  | \$ 127.80                  | \$ 63.90              |
| 27    | 1 pc  | Rr end panel                   | Dented          |           | \$ 440.50                  | \$ 440.50             |
| 28    | 1 pc  | Rr end panel garnish           | Dented/Deformed |           | \$ 401.80                  | \$ 401.80             |
| 29    | 2 pcs | Rr fender inner trim R/L       | Dented/Deformed | \$ 833.80 | \$ 1,667.60                | \$ 1,667.60           |
| 30    | 1 pc  | Rr compartment cover           | Dented/Deformed |           | \$ 800.40                  | \$ 800.40             |
| 31    | 1 pc  | Rr floor panel                 | Dented          |           | \$ 804.30                  | \$ 804.30             |
| 32    | 1 pc  | Rr floor panel lining          | Torn/Deformed   |           | \$ 437.10                  | \$ 437.10             |
| 33    | 1 pc  | Rr floor panel reinforcement   | Bent/Necessary  |           | \$ 110.50                  | \$ 110.50             |
| 34    | 1 pc  | Rr floor panel bracket         | Necessary       |           | \$ 72.10                   | \$ 72.10              |
| 35    | 1 pc  | Exhaust silencer               | Refit           |           | \$ 1,031.10                | \$ -                  |
|       |       |                                |                 |           | \$ 13,003.60               | \$ 9,216.60           |
|       |       |                                |                 |           | Less Discount : 25%        | 25%                   |
|       |       |                                |                 |           | \$ 3,250.90                | \$ 2,304.15           |
|       |       |                                |                 |           | List Parts Sub-Total :     | \$ 9,752.70           |
|       |       |                                |                 |           |                            | \$ 6,912.45           |
| 1     | 1 pc  | Rr windscreen sealant          | Necessary       | S/N       | \$ 50.00                   | \$ 40.00              |
| 2     | 1 set | Rr no.plate (w/bracket)        | Dented/Cracked  | S/N       | \$ 50.00                   | \$ 50.00              |
| 3     | 1 set | Rr reverse sensor (4pcs type)  | Dented/Damaged  | S/N       | \$ 400.00                  | \$ 350.00             |
| 4     | 1 pc  | Rr end panel sealant           | Necessary       | S/N       | \$ 50.00                   | \$ 40.00              |
| 5     | 1 pc  | Rr floor panel sealant         | Necessary       | S/N       | \$ 50.00                   | \$ 40.00              |
|       |       |                                |                 |           | Special Nett Sub-Total :   | \$ 600.00             |
|       |       |                                |                 |           |                            | \$ 520.00             |
|       |       |                                |                 |           | Parts Total :              | \$ 10,352.70          |
|       |       |                                |                 |           |                            | \$ 7,432.45           |



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No. : SGP4001D

Report No. : PAS/TP/0220616

| S/No.                    | Labour Descriptions  | Repairer's Estimate (\$) | Our Assessment (\$) |
|--------------------------|--|--------------------------|---------------------|
| 1                        | To check rear electrical wiring system.  | \$ 80.00                 | \$ 50.00            |
| 2                        | To transfer rear windscreen to new tailgate.   | \$ 150.00                | \$ 120.00           |
| 3                        | To transfer tailgate component parts to new tailgate.                                      | \$ 120.00                | \$ 100.00           |
| 4                        | To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. | \$ 250.00                | \$ 220.00           |
| 5                        | To remove and reinstall exhaust silencer for necessary.                                    | \$ 150.00                | \$ 120.00           |
| 6                        | To remove, replace and reinstall rear reverse sensors & control unit.                      | \$ 80.00                 | \$ 60.00            |
| 7                        | To straighten, repair, realign on affected area and replace damaged parts.                 | \$ 1,800.00              | \$ 1,540.00         |
| 8                        | To conduct chassis alignments.   | \$ 400.00                | \$ 300.00           |
| 9                        | To spray painting on affected area.  | \$ 1,500.00              | \$ 1,300.00         |
| 10                       | To spray anti-rust coating on new and affected panels.                                     | \$ 200.00                | \$ 150.00           |
| Labour Total :           |  | \$ 4,730.00              | \$ 3,960.00         |
| Total (Parts & Labour) : |  | \$ 15,082.70             | \$ 11,392.45        |

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,650.00

Under normal circumstances, the repairs should be completed within a reasonable period of **12 Working Days**.

82 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

