



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD	Cust No/Name LC000162/ CYCLE & CARRIAGE LEASING PTE L
239 ALEXANDRA ROAD	Reg No/Reg Date SMM3307Z / 26/06/201
SINGAPORE 159930	Date In/Mileage / 85665
Contact No Mobile: 85188668	Chassis No KNAF1416MK5047620
	Engine No G4FGKH741994
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	27/07/2020/ 13:10	QUD	247 / DonBong	18375			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2200 3300.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, CUT/WELD RH REAR FENDER, REPAIR RH REAR FENDER								
E PNT88000								300.00
REMOVE AND REPLACE REAR WINDSCREEN GLASS								
M SUNDRY								80.00
SUPPLY REAR WINDSCREEN SEALANT								
E PNT88000								80 100.00
REMOVE AND INSTALL PARKING ASSIST								
E PNT98000								1260 1680.00
PAINT WORK SPRAY REAR BUMPER FACE, RH REAR FENDER, RH REAR DOOR AND AFFECTED PORTION								
M SUNDRY								80 160.00
SUPPLY BODY SEALANT								
A 54900099								50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								80 160.00
PERFORM RUST PREVENTION								
A 10028901								200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
A 20000001								550.00
RENEW REAR UNDERCARRIAGE DAMAGES								
M SUNDRY								sur 450.00
SUPPLY RH REAR SPORT RIM S890								
M SUNDRY								30.00
LABOUR RENEW RH REAR SPORT RIM INCLUDING BALANCING								
A WHEELALIGNMENTBP								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								Xan? 220.00
SUPPLY REAR WINDSCREEN SOLAR FILM								
M SUNDRY								20 50.00
SUNDRIES								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD	Cust No/Name LC000162/ CYCLE & CARRIAGE LEASING PTE L
239 ALEXANDRA ROAD	Reg No/Reg Date SMM3307Z / 26/06/201
SINGAPORE 159930	Date In/Mileage / 85665
Contact No Mobile: 85188668	Chassis No KNAF1416MK5047620
	Engine No G4FGKH741994
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	27/07/2020/ 13:10	QUD	247 / DonBong	18375			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-QUARTER OUTER, RH	bue✓			1.00	1349.00	00.00	1349.00✓
M	PANEL ASSY-RR COMB LAMP HSG, RH	? x su✓			1.00	135.00	00.00	135.00
M	GLASS ASSY-REAR WINDOW	? photo x su✓			1.00	447.00	00.00	447.00
M	BRACKET ASSY-RR BPR SIDE UPR, L	x su✓			1.00	25.00	00.00	25.00
M	BRACKET-ASSY RR BPR SIDE UPR, R	? ch ✓			1.00	31.00	00.00	31.00✓
M	COVER-RR BUMPER UNDER, RH	x su✓			1.00	33.00	00.00	33.00
M	GROMMET ASSY-SCREW	ne ✓			2.00	2.00	00.00	4.00✓
M	CLIP	ne ✓			10.00	1.00	00.00	10.00✓
M	COVER-RR BUMPER	de ✓			1.00	651.00	00.00	651.00✓
M	COVER-RR BUMPER LWR	x su✓			1.00	241.00	00.00	241.00
M	HANDLE ASSY-DOOR OUTSIDE, RH	repair			1.00	58.00	00.00	58.00
M	COVER-FR DR O/S HDL RH	x su✓			1.00	14.00	00.00	14.00
M	HUB & BEARING ASSY-RR	? h ✓			1.00	437.00	00.00	437.00✓
M	TORSION AXLE COMPLETE	? h ✓			1.00	1031.00	00.00	1031.00✓

SURVEYOR NAME:

Rasul - Hp 90010068

SURVEYOR SIGNATURE:

R

DATE:

28/07/2020 @ 1050

REMARKS:

9 days

Repair before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm & accepted by:

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	11,916.00
7% GST on	11916.00	834.12
Total Payable		12,750.12

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO. : GAIG

Supplementary For Registration No.: SMM 3307 Z

<u>Materials</u>		<u>Cost (\$)</u>
1	Film- Anti Chippg RH NEC /	27.00
	7% GST	1.89
	Total	28.89

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258