

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20007746/R1PS3Q2

**Date:** 15/10/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0000376_02
<b>Claimant Vehicle No :</b>	SLQ550Y	<b>Insured Vehicle No :</b>	SKL3383G
Date of Loss:	26/07/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001420

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLQ550Y</b>		
Make & Model:	LAND ROVER DISCOVERY SPORT, 2.0 D 7-SEATER (180PS) (A)	Engine No:	180105Y0364PT204
Reg. Date:	24/09/2018 (Man. Year: 2018)	Chassis No:	SALCA2AX8JH751358
Colour:	White	Odometer:	25001 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,890.82	3,024.09	6,866.73	69.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,925.00	2,725.00	6,200.00	69.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,815.82</b>	<b>5,749.09</b>	<b>13,066.73</b>	<b>69.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,317.11</b>	<b>402.44</b>	<b>914.67</b>	<b>69.45</b>
<b>Nett Amount (S\$)</b>	<b>20,132.93</b>	<b>6,151.53</b>	<b>13,981.40</b>	<b>69.45</b>
<b>+ Car Rental (3.0 x S\$130.00/day + 7.00% GST) (S\$)</b>		<b>417.30</b>		
	<b>Nett Liability (S\$)</b>	<b>6,568.83</b>		

### INSPECTION

Date of Assignment:	28/07/2020	
Date Inspected:	24/08/2020 Inspected At:	45 LENG KEE ROAD
		Repairer: Wearnes Automotive Pte Ltd (Leng Kee)
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Sep 2020)	
<b>Parts:</b>	N/A	LAND ROVER DISCOVERY SPORT 2.0 D 7-SEATER (180PS) (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ550Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LLR106865/BUMPER -R	Cut	1,723.80 FS	*1,551.42 FS
2	1		*TOW EYE COVER REAR D	Scratched	557.80 FS	*502.02 FS
3	1		*LLR104912/REINFORCEM	Serviceable	625.70 FS	*- FS
4	1		*BRACKET -BUMPER MOU	Serviceable	121.10 FS	*- FS
5	1		*SENSOR -PARKING AID (4 PCS)	Cut (1 PCS ONLY)	1,541.60 FS	*346.86 FS
6	1		*LAMP -FOG -REAR RH	Cracked	354.10 FS	*318.69 FS
7	1		*MOULDING -REAR WHEE	Serviceable	312.70 FS	*- FS
8	1		*MUFFLER -REAR	Serviceable	2,797.00 FS	*- FS
9	1		*CLAMP	Serviceable	186.90 FS	*- FS
10	1		*BADGE REAR DISCO D	Not Necessary	167.10 FS	*- FS
11	1		*BADGE REAR VERY DS	Not Necessary	149.90 FS	*- FS
12	1		*BADGE OVAL REAR RR3	Not Necessary	89.00 FS	*- FS
13	2		*ADHESIVE AND SEALER	Necessary	310.20 FS	*279.18 FS
14	1		*BODY PANEL SEALANT	Not Necessary	928.00 FS	*- FS
15	1		*TOW HOOK COVER REAR	Deformed	25.92 FS	*25.92 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>9,890.82      3,024.09</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE REAR BUMPER ,TOW COVER ,REPAIR REAR BOOTLID	New	3,600.00	1,200.00
2	TO PUTTY SPRAYPAINT ON REAR BUMPER ,REAR BOOTLID	New	3,000.00	1,000.00
3	TO REPLACE REAR RH DIFFUSER AS	New	1,800.00	0.00
4	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	New	525.00	525.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,925.00</b>	<b>2,725.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >