

SERVICE ESTIMATE

98404 - C00001 SL: SERVICE SALES - PC
 Mr Chia Eng Hoo
 BLK 207 Pasir Ris Street 21
 #08-364
 Singapore 510207

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 27/07/2020
 WIP No. . : 30595
 Veh.In/Out:
 *Tel.No. . : Mobile: 96377763
 Reg.No. . : SLQ550Y
 Reg.date . : 24/09/2018
 Mileage . : 0
 Chassis No: SALCA2AX8JH751358

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Chia Eng Hoo

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
302	TO REPLACE REAR BUMPER, TOW COVER, REPAIR REAR BOOTLID	0	3600.00	0		3,600.00 S	1200
300	TO PUTTY SPRAYPAINT ON REAR BUMPER, REAR BOOTLID	0	3000.00	0		3,000.00 S	1000
302	TO REPLACE REAR RH DIFFUSER AS	0	1800.00	0		1,800.00 S	900?
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	525.00	0		525.00 S	
	LLR106865/BUMPER - R <i>cut</i>	1.0 EA	1723.80			1,723.80 S	
	TOW EYE COVER REAR D <i>scu</i>	1.0 EA	557.80			557.80 S	
	LLR104912/REINFORCEM <i>?</i>	1.0 EA	625.70			625.70 S	
	BRACKET - BUMPER MOU <i>?</i>	1.0 EA	121.10			121.10 S	
	SENSOR - PARKING AID <i>cut</i>	1.0 EA	385.40			1,541.60 S	
	LAMP - FOG - REAR RH <i>cut</i>	1.0 EA	354.10			354.10 S	
	MOULDING - REAR WHEEL <i>?</i>	1.0 EA	312.70			312.70 S	
	MUFFLER - REAR <i>?</i>	1.0 EA	2797.00			2,797.00 S	
	CLAMP <i>?</i>	1.0 EA	186.90			186.90 S	

SERVICE ESTIMATE

98404 - C00001 SL: SERVICE SALES - PC

Mr Chia Eng Hoo
BLK 207 Pasir Ris Street 21
#08-364

Singapore 510207

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Chia Eng Hoo

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 27/07/2020

WIP No. . : 30595

Veh.In/Out:

*Tel.No. . : Mobile: 96377763

Reg.No. . : SLQ550Y

Reg.date. : 24/09/2018

Mileage . : 0

Chassis No: SALCA2AX8JH751358

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BADGE REAR "DISCO" D X	1.0 EA	167.10			167.10	S
	BADGE REAR "VERY" DS X	1.0 EA	149.90			149.90	S
	BADGE OVAL REAR RR3 X	1.0 EA	89.00			89.00	S
	ADHESIVE AND SEALER <i>rec</i>	2.0 EA	155.10			310.20	S
	BODY PANEL SEALANT X X	1.0 EA	928.00			928.00	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total 8,925.00
Parts Total 9,864.90
Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Gross Total. 18,789.90

Net..... 18,789.90

GST @ 7.0% 1,315.29

Total..... 20,105.20

Paid..... 0.00

Please Pay.. 20,105.20

Ram
Hp 90010068
3 days
28/08/2020 @ 1600
Resurvey before paint