

### SERVICE ESTIMATE

98404 - C00001      SL: SERVICE SALES - PC

Mr Chia Eng Hoo

BLK 207 Pasir Ris Street 21

#08-364

Singapore 510207

Closed by .... : Paul Ong Qing Yong

Svc Consultant :

Remarks ..... : Mr Chia Eng Hoo

GST Reg.No:M28920628X

Inv.No. . : B&P      0      Page 1

Inv.date. : 27/07/2020

WIP No. . : 30595

Veh.In/Out:

\*Tel.No. . : Mobile: 96377763

Reg.No. . : SLQ550Y

Reg.date . : 24/09/2018

Mileage . : 0

Chassis No: SALCA2AX8JH751358

| Op.No | Description                    | Mech Qty | Price   | Disc% | Pkg | Amount   | G |
|-------|--------------------------------|----------|---------|-------|-----|----------|---|
| 802   | TO REPLACE REAR BUMPER,        | 0        | 3600.00 | 0     |     | 3,600.00 | S |
|       | TOW COVER, REPAIR REAR BOOTLID |          |         |       |     |          |   |
| 800   | TO PUTTY SPRAYPAINT ON         | 0        | 3000.00 | 0     |     | 3,000.00 | S |
|       | REAR BUMPER, REAR BOOTLID      |          |         |       |     |          |   |
| 802   | TO REPLACE REAR RH DIFFUSER AS | 0        | 1800.00 | 0     |     | 1,800.00 | S |
| 280   | TO CHECK WIRING INCLUDE        | 0        | 525.00  | 0     |     | 525.00   | S |
|       | RESETTING OF ALL ELECTRICAL    |          |         |       |     |          |   |
|       | MODULES                        |          |         |       |     |          |   |
|       | LLR106865/BUMPER - R           | 1.0 EA   | 1723.80 |       |     | 1,723.80 | S |
|       | TOW EYE COVER REAR D           | 1.0 EA   | 557.80  |       |     | 557.80   | S |
|       | LLR104912/REINFORCEM           | 1.0 EA   | 625.70  |       |     | 625.70   | S |
|       | BRACKET - BUMPER MOU           | 1.0 EA   | 121.10  |       |     | 121.10   | S |
|       | SENSOR - PARKING AID           | 4.0 EA   | 385.40  |       |     | 1,541.60 | S |
|       | LAMP - FOG - REAR RH           | 1.0 EA   | 354.10  |       |     | 354.10   | S |
|       | MOULDING - REAR WHEE           | 1.0 EA   | 312.70  |       |     | 312.70   | S |
|       | MUFFLER - REAR                 | 1.0 EA   | 2797.00 |       |     | 2,797.00 | S |
|       | CLAMP                          | 1.0 EA   | 186.90  |       |     | 186.90   | S |

### SERVICE ESTIMATE

98404 - C00001      SL: SERVICE SALES - PC

Mr Chia Eng Hoo

BLK 207 Pasir Ris Street 21

#08-364

Singapore 510207

GST Reg.No:M28920628X

Inv.No. . : B&P      0    Page 2

Inv.date. : 27/07/2020

WIP No. . : 30595

Veh.In/Out:

\*Tel.No. . : Mobile: 96377763

Reg.No. . : SLQ550Y

Reg.date. : 24/09/2018

Mileage . : 0

Chassis No: SALCA2AX8JH751358

Closed by .... : Paul Ong Qing Yong

Svc Consultant :

Remarks ..... : Mr Chia Eng Hoo

| Op.No | Description          | Mech Qty | Price  | Disc% | Pkg | Amount | G |
|-------|----------------------|----------|--------|-------|-----|--------|---|
|       | BADGE REAR "DISCO" D | 1.0 EA   | 167.10 |       |     | 167.10 | S |
|       | BADGE REAR "VERY" DS | 1.0 EA   | 149.90 |       |     | 149.90 | S |
|       | BADGE OVAL REAR RR3  | 1.0 EA   | 89.00  |       |     | 89.00  | S |
|       | ADHESIVE AND SEALER  | 2.0 EA   | 155.10 |       |     | 310.20 | S |
|       | BODY PANEL SEALANT X | 1.0 EA   | 928.00 |       |     | 928.00 | S |

Gross Total.      18,789.90

Labour Total      8,925.00  
 Parts Total      9,864.90  
 Package Total      0.00

Net.....      18,789.90  
 GST @ 7.0%      1,315.29  
 Total.....      20,105.20  
 Paid.....      0.00  
 Please Pay..      20,105.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated