

SERVICE ESTIMATE

98404 - C00001 SL: SERVICE SALES - PC
Mr Chia Eng Hoo
BLK 207 Pasir Ris Street 21
#08-364

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
Inv.date. : 27/07/2020
WIP No. : 30595
Veh.In/Out:

Singapore 510207

*Tel.No. : Mobile: 96377763

Reg.No. : SLQ550Y

Reg.date : 24/09/2018

Mileage : 0

Chassis No: SALCA2AX8JH751358

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Chia Eng Hoo

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER,	0	3600.00	0	3,600.00	S	1200
	TOW COVER, REPAIR REAR BOOTLID	0	3000.00	0	3,000.00	S	1000
800	TO PUTTY SPRAYPAINT ON	0	1800.00	0	1,800.00	S	900? XM
	REAR BUMPER, REAR BOOTLID	0	525.00	0	525.00	S	
802	TO REPLACE REAR RH DIFFUSER AS	0					
280	TO CHECK WIRING INCLUDE	0					
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	LLR106865/BUMPER - R	1.0 EA	1723.80		1,723.80	S	1551.42
	TOW EYE COVER REAR D	1.0 EA	557.80		557.80	S	502.02
	LLR104912/REINFORCEM	1.0 EA	625.70		625.70	S	
	BRACKET - BUMPER MOU	1.0 EA	121.10		121.10	S	
	SENSOR - PARKING AID	1.0 EA	385.40		1,541.60	S	346.86
	LAMP - FOG - REAR RH	1.0 EA	354.10		354.10	S	318.69
	MOULDING - REAR WHEE	1.0 EA	312.70		312.70	S	
	MUFFLER - REAR	1.0 EA	2797.00		2,797.00	S	
	CLAMP	1.0 EA	186.90		186.90	S	

ACCIDENT STATEMENT

SERVICE ESTIMATE

98404 - C00001 SL: SERVICE SALES - PC

Mr Chia Eng Hoo
BLK 207 Pasir Ris Street 21
#08-364

GST Reg.No:M28920628X

25/07/2020 10:05

PIE NEAR T

SINGAPORE

Inv.No. : B&P 0 Page 2

Inv.date. : 27/07/2020

WIP No. : 30595

Veh.In/Out:

Singapore 510207

SLQ550Y

*Tel.No. : Mobile: 96377763

Reg.No. : SLQ550Y

Reg.date. : 24/09/2018

Mileage : 0

Chassis No: SALCA2AX8JH751358

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Chia Eng Hoo

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

BADGE REAR "DISCO" D X^{an}

1.0 EA 167.10 167.10 S

BADGE REAR "VERY" DS X^{an}

1.0 EA 149.90 149.90 S

BADGE OVAL REAR RR3 X^{an}

1.0 EA 89.00 89.00 S

ADHESIVE AND SEALER rec/

2.0 EA 155.10 310.20 S

BODY PANEL SEALANT X X^{an}

1.0 EA 928.00 928.00 S

279.18

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Gross Total. 18,789.90

Net..... 18,789.90

GST @ 7.0% 1,315.29

Total..... 20,105.20

Paid..... 0.00

Please Pay.. 20,105.20

Labour Total 8,925.00

Parts Total 9,864.90

Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Resur
Hp 9000w68
3 days
24/08/2020 @ 1600
Resurvy be for paint

supp

SERVICE ESTIMATE

0 - I00012 SL: INDIA INTERNATIONAL INSURANCE
 INDIA INTERNATIONAL INSURANCE GST Reg.No:M28920628X
 64 CECIL ST Inv.No. . : B&P 0 Page 1
 #04-05 IOB BUILDING Inv.date. : 10/09/2020
 SINGAPORE 049711 WIP No. . : 30595
 Veh.In/Out: 24/08/2020 28/08/2020
 *Tel.No. . : 6347 6100
 Reg.No. . : SLQ550Y
 Closed by : Paul Ong Qing Yong Reg.date . : 24/09/2018
 Svc Consultant : ACC Mileage . : 23,559
 Remarks : Mr Chia Eng Hoo Chassis No: SALCA2AX8JH751358

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TOW HOOK COVER REAR de/	1.0 EA	28.80	10		25.92	S

Labour Total	0.00
Parts Total	25.92
Package Total	0.00

Gross Total.	25.92
Net.....	25.92
GST @ 7.0%	1.81
Total.....	27.73
Paid.....	0.00
Please Pay..	27.73

GST: S=StdRated; O=OutOfScope; Z=ZeroRated