

ASS. REG BY:

REF:

Smo/

Kenrick

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO/TP/NS/LP/RES/CO/RES/EVA/INV/INV

To inspect Vehicle No: _____

at Workshop no: HC

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: 07 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: 7/22 Person Contacted: _____ Vehicle: IN/OUT

Veh No: SLP 21894 Yr Regn: 09, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Carry C.G. 1998

Colour: MP. White A/C: Insured / Std / NI / NA

Sp. Reading: 328431 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: MR 0538K410 7015733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pavanti

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 3 mm

L/Bal. 4 mm L/Bal. 3 mm

D.O.A. 27/7/20 D.O.I. 28/7/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S FR & 46

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Call not ready</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: 7
Resurvey No. of Trip: 2

1/9/20-Typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	_____
Transportation:	_____
S - RS - SI	_____
Fuel	_____
Others	_____
TOTAL	_____

Report Format: TP
Lump Sum H.B.F: (\$ 9650)

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co and GST Reg. No. : 200820153N

Date : 28 / 07 / 2020

ESTIMATE	COSTS	OF REPAIR
----------	-------	-----------

M/s SJ Motor Enterprise

C/o 160 Sin Ming Drive
05-09 Sin Ming Auto City
Singapore 575722

*Not withold
1/1 Smg &
Resurvey After Paint
7 days*

Dear Sir / Madam ,

Vehicle no. : SLP 2169 H - Toyota Camry 2.0 (A)
Accident date : 27 / 07 / 2020

Quantity	Descriptions	Amount (S\$)	
1	1 pc bonnet	\$ <i>By</i> 1,028.75	✓
2	1 pc n/s bonnet hinge	\$ <i>DIY</i> 52.60	✓
3	1 pc front grille	\$ <i>CM</i> 549.80	✓
4	1 pc n/s head lamp	\$ <i>By</i> 1,810.80	✓
5	1 pc n/s head lamp lower bracket	\$ <i>DIY</i> 98.35	✓
6	1 pc front bumper fascia	\$ <i>CM</i> 1,923.10	✓
7	1 pc front bumper sponge	\$ <i>Sm</i> 102.00	X
8	1 pc front bumper reinforcement	\$ <i>R</i> 511.30	X
9	1 pc n/s front bumper side retainer	\$ <i>CM</i> 60.30	✓
10	1 pc n/s front bumper chrome moulding (near fog lamp)	\$ <i>Mc</i> 150.03	✓
11	1 pc n/s fog lamp	\$ 292.30	?
12	1 pc n/s front fog lamp cover	\$ <i>Mc</i> 150.50	X
13	5 pcs front bumper clip 1 @ 3.50	\$ <i>Mc</i> 17.50	✓
14	1 pc n/s front fender	\$ <i>By</i> 800.50	✓
15	1 pc n/s front fender 'VVT-i' emblem	\$ <i>Mc</i> 83.60	✓
16	1 pc n/s front fender inner garnish	\$ <i>CM</i> 153.20	✓
17	11 pcs n/s front fender inner garnish clips 1 @ 3.00	\$ <i>Mc</i> 33.00	✓
18	1 pc n/s front fender top garnish	\$ <i>my</i> <i>DIY</i> 202.70	✓
19	1 pc n/s front fender inner sponge	\$ 187.70	?
20	1 pc front support panel	\$ <i>By</i> 959.70	✓
21	1 pc n/s front door	\$ 1,087.09	?
22	2 pcs n/s front door hinge 1 @ 75.61	\$ <i>R</i> 151.22	X
23	1 pc n/s front rocker panel	\$ <i>R</i> 480.12	X
24	1 pc n/s front rocker panel garnish	\$ <i>By</i> 617.87	✓
25	1 pc n/s front shocker absorber	\$ 425.90	?
26	1 pc n/s front lower arm	\$ 602.00	?
27	1 pc n/s front knuckle arm	\$ <i>By</i> 583.60	✓
28	1 pc n/s front knuckle arm bearing	\$ <i>Mc</i> 171.70	✓
Balance C/FD		\$ 13,287.23	

H C AUTO PTE LTD

160 Sin Ming Drive # 03-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co and GST Reg. No. : 200820153N

		Balance B/FD (SLP 2169 11)		\$	13,287.23	
29	1 pc	n/s front anti roll bar side link		\$	181.36	7
30	1 pc	n/s front drive shaft		\$	1,930.20	7
				\$	15,398.79	
		Less 25 %		\$	3,849.70	
				\$	11,549.09	
31	1 pc	n/s front wheel tyre	<i>Pu</i>	\$	385.00	sn 20Wm
32	1 pc	n/s front wheel rim	<i>nd</i>	\$	1,200.00	sn 38Wm
				\$	13,134.09	
		Labour charges		\$	1,800.00	700l
		To putty and spray painting		\$	1,600.00	1200l
		Re-seal anti rust		\$	200.00	90l
		Towing fee		\$	120.00	50l
		To check, replace, repair wiring		\$	120.00	30l
		To check wheel alignment		\$	120.00	60l
		Remove and refix n/s front undercarriage		\$	450.00	180l
				\$	17,544.09	
		Plus 7 % GST		\$	1,228.09	
		Grand total		\$	18,772.18	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Business
Owner ID:	801X
Vehicle Details	
Vehicle No.:	SLP2169H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Jul 2020
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	1AZE055347
Chassis No.:	MR053BK4107015733
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$26,761.00
Original Registration Date:	19 Sep 2007
First Registration Date:	19 Sep 2007
Transfer Count:	3
Actual ARF Paid:	\$29,438.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,237.00
COE Rebate Amount:	\$10,551.00
Total Rebate Amount:	\$10,551.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Jul 2020

OK