

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Adress : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimate

TP CLAIM

To : **AIG Asia Pacific Insurance Pte Ltd**
 Motor Claims Dept

Date : 31 Aug 20

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR MERCEDES BENZ 316CD - SKW1219D
ACCIDENT INVOLVING SKW1219D & SFC1860R ON 26/07/2020

| <u>ITEMS</u> | <u>DESCRIPTION</u> | <u>QTY</u> | <u>PRICE</u> |
|--------------|---|------------|------------------------|
| 1 | Front fender n/s | 1pc | \$ 473.75 bl ✓ |
| 2 | Front fender lamp n/s | 1pc | \$ 103.88 cr a ✓ |
| 3 | Front fender lower protector n/s | 1pc | \$ 255.63 cut ✓ |
| 4 | Nut @\$2.92ea | 2pcs | \$ 5.84 ne ✓ |
| | | | \$ 839.10 |
| | Less 10% | | \$ (83.91) |
| | | | \$ 755.19 ✓ |
| | <u>Labour Charge & Misc</u> | | |
| | To remove, repair, replace & install damaged parts. | } | \$ 450.00 250 |
| | | } | |
| | To R & R wiring. | | \$ 60.00 30 |
| | To numbering logo | | \$ 350.00 200 |
| | To putty & spray painting. | | \$ 400.00 250 |
| | Total | | \$ 2,015.19 730 |

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Taufik 97495749
 - WP - 31/8/20 \$1485.19
 P/P Resurvey before paint 3 days
 o 3 days
 taufik@lkkauto.com .