

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
 Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautop@gmail.com

SIE: _____ Vehicle Nos: **SDY 6269 Z**
 Date of Survey: _____ Model: Nissan Sunny
 Date of ReSurvey: _____ After-Paint: _____ Year: _____
 Contacts: _____ Chassis No: _____

*** AGREED Cost Of Repair and Repair Day/s with SIE ***
 Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit \$S	TOTAL \$S	
1	Bootlid	1	\$ 782.60	\$ 782.60	DDV
2	Bootlid logo	1	\$ 108.90	\$ 108.90	DDV
3	Bootlid emblem 'Sunny'	1	\$ 118.60	\$ 118.60	DDV
4	Bootlid emblem 'EX Saloon'	1	\$ 103.60	\$ 103.60	DDV
5	Bootlid emblem 'CVT'	1	\$ 97.00	\$ 97.00	DDV
6	Bootlid emblem 'E-Throttle'	1	\$ 69.00	\$ 69.00	DDV
7	Bootlid outer chrome garnish	2	\$ 486.20	\$ 972.40	BRV
8	Bootlid inner trim board	1	\$ 198.30	\$ 198.30	NDX
9	Bootlid number plate lamp	2	\$ 86.40	\$ 172.80	NDX
10	Bootlid weatherstrip	1	\$ 286.30	\$ 286.30	DDV
11	Bootlid hinge	1	\$ 186.90	\$ 186.90	DDV
12	Bootlid lock	1	\$ 214.50	\$ 214.50	DDV
13	Bootlid striker	1	\$ 96.40	\$ 96.40	DDV
14	Rear bumper	1	\$ 595.20	\$ 595.20	DDV
15	Rear bumper outer chrome moulding	1	\$ 184.60	\$ 184.60	DDV
16	Rear bumper side retainer	2	\$ 87.40	\$ 174.80	DDV
17	Rear bumper reinforcement stopper	2	\$ 168.00	\$ 336.00	DDV
18	Rear end panel	1	\$ 583.60	\$ 583.60	DDV
19	Rear end panel top garnish	1	\$ 196.50	\$ 196.50	DDV
20	Rear fender	1	\$ 788.60	\$ 788.60	DDV
21	Rear fender inner trim board	2	\$ 214.90	\$ 429.80	DDV
22	Rear fender air vent	1	\$ 181.50	\$ 181.50	DDV
23	Rear windscreen moulding	1	\$ 184.20	\$ 184.20	DDV
24	Spare tyre panel	1	\$ 898.60	\$ 898.60	DDV
25	Spare tyre top board	1	\$ 241.80	\$ 241.80	DDV
26	Taillamp	2	\$ 432.40	\$ 864.80	DDV
27	Taillamp lower bracket	2	\$ 65.40	\$ 130.80	DDV
28	Taillamp base panel	2	\$ 214.80	\$ 429.60	DDV
29	Exhaust pipe	1	\$ 855.00	\$ 855.00	DDV
30	Exhaust mounting	1	\$ 79.50	\$ 79.50	DDV
Parts Sub Total:				\$ 4738.40	\$ 4738.40
10% Discount:				\$ 473.84	\$ 473.84
PARTS TOTAL:				\$ 4264.56	\$ 4264.56

SDY 62632

Nos.	SPECIAL NETT	Qty	Unit	SS	TOTAL SS		
1	Sundries	1	\$	80.00	\$	-80.00	NHX
2	Boottlid sealant	1	\$	100.00	\$	100.00	
3	Boottlid outer chrome garnish clips	2	\$	50.00	\$	100.00	NFC
4	Rear end panel sealant	1	\$	100.00	\$	100.00	
5	Rear bumper clips	1	\$	50.00	\$	-50.00	
6	Rear end panel sealant	1	\$	100.00	\$	-100.00	RPT
7	Rear end panel top garnish clips	1	\$	50.00	\$	-50.00	
8	Rear fender sealant	2	\$	100.00	\$	-200.00	NEC
9	Rear fender lower trim board clips	2	\$	50.00	\$	-100.00	NHX
10	Rear windscreen seal	1	\$	60.00	\$	60.00	
11	Rear windscreen sealant	1	\$	100.00	\$	100.00	NHX
12	Rear windscreen primer and cleaner	1	\$	80.00	\$	80.00	
13	Spare tyre panel sealant	1	\$	100.00	\$	-100.00	NECC
14	Taillamp clips	2	\$	50.00	\$	-100.00	NHX
15	Taillamp seal	2	\$	60.00	\$	-120.00	
16	Taillamp base panel sealant	1	\$	100.00	\$	100.00	NECC
17	Rear number plate w/cowling	1	\$	80.00	\$	80.00	BT
18	Reverse sensor with module	2	\$	250.00	\$	500.00	BC
19	Breakdown sign	1	\$	120.00	\$	120.00	NHX
SPECIAL NETT TOTAL:					\$ 730.00	\$ 2,240.00	

Nos.	LABOUR	SS	
1	R&R bootlid component	\$ 550.00	100.00
2	R&R reverse sensor and spray paint	\$ 60.00	100.00
3	R&R exhaust pipe	\$	150.00
4	R&R fuel pipe	\$	100.00
5	R&R rear windscreen	\$	100.00
6	Washers	\$	100.00
7	Check wiring	\$ 300.00	100.00
8	Conduct water leakage test	\$	100.00
9	Rust proofing	\$ 60.00	100.00
10	Spray painting	\$ 2,000.00	1,800.00
11	Panel beat	\$ 1,000.00	1,800.00
LABOUR TOTAL:		\$ 2,460.00	5,050.00

Survey 28/3/2020
Total hrs 1430 hrs

Re-survey => 4/10/2020
Total hrs 1315 hrs

ump sun repair
Repair days 3

PARTS TOTAL:	\$ 4318.56	10,383.93
SPECIAL NETT TOTAL:	\$ 730.00	2,240.00
LABOUR TOTAL:	\$ 2,460.00	5,050.00
GRAND TOTAL:	\$ 7448.56	17,673.93
	7448.56	
	1489.71	
	5958.85	

L/S 5958/2

TJGM
18/10/20

LXX Auto Conciliators hereby notify the Repairer of the following:

- To recovery before/after spray painting
- To (re) damaged part(s) during recovery
- Parts price are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No legal indemnity is allowed
- Supplementary terms must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____