



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD19021796/Esf3e2-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 05-08-2020



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 6964B	Veh. Inspected	GBG 5345L
Policy No.	PNPV2018-00004110-01	Coverage (\$)	0.00
Claim No.	1201900039153	Excess (\$)	0.00
Assign From	JOSEY LOH	Assign Date	13/07/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFHT02P900231815	Colour	SILVER
Odometer	93110	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	4 mm
L/H Front Tyre	195 R15C	MICHELIN	4 mm
R/H Rear Tyre	195 R15C	MICHELIN	4 mm
L/H Rear Tyre	195 R15C	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/12/2019	Inspection Date	10/12/2019
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------