

Not Authorized
 6/18/20
 Resurvey After Paint

TAI CHENG MOTOR VEHICLE SPRAY PAINTING
 10 ANG MO KIO INDUSTRIAL PARK 2A #01-03
 ANG MO KIO AUTOPOINT SINGAPORE 568047
 TEL: 64835595, H/P:96365090 FAX: 64835895
 Business Registration No: 234718/00E
 GST Registration No: 23-471800-E
 Email: shchua@taichengmotor.com

YOUR REF:
OUR REF:

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #09-16
SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT
POLICY NO: 2070064703
REG. NO: GBH3943T
OWNER: RH2S DECO CURTAINS
TYPE: TOYOTA HIACE

DATE: 28.07.20

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost of repair to damaged vehicle accident on 24.06.20

Description	quantity	Price	
front windscreen glass	1	\$ CM 1,379.50	✓
windscreen side moulding	1	\$ M 62.30	✓
front wiper panel garnish	1	\$ M 495.10	✓
wiper panel corner garnish o/s	1	\$ M 26.80	✓
corner panel top inner rubber	1	\$ G 33.50	✓
front bonnet	1	\$ B 756.60	✓
bonnet emblem	1	\$ M 66.20	✓
bonnet hinge	2	\$. 97.80	✓
bonnet inner lower corner rubber o/s	1	\$ M 41.70	✓
front grille top	1	\$ M 191.50	✓
front grille lower	1	\$ M 330.80	✓
front grille base	1	\$ M 491.10	✓
front bumper	1	\$ CM 496.40	✓
front bumper grille centre	1	\$ M 154.30	✓
front bumper fog lamp granish o/s	1	\$ M 58.10	✓
front bumper lower reinforcement	1	\$ B 304.40	✓
front bumper top reinforcement beam	1	\$ B 159.10	✓
bumper vertical reinforcement bracket o/s	1	\$ D 54.50	✓
front headlamp	1	\$ B 848.70	✓
front support panel	1	\$ B 333.60	✓
front brace panel	1	\$ R 43.40	X
front chassis front bracket o/s	1	\$ 422.10	?
bumper tow hook cover	1	\$ M 26.70	✓
air con condensor	1	\$ 1,216.10	?
radiator	1	\$ 2,317.20	?
radiator fan cowling	1	\$ 266.30	?
chassis front side member o/s	1	\$ R 1,293.70	?
air con suction pipe front	1	\$ 464.60	?
air con suction pipe rear	1	\$ 662.70	?
air con liquid pipe	1	\$ 262.70	?
air con delivery pipe	1	\$ 298.40	?
air con discharge pipe front	1	\$ 344.80	?
air con discharge pipe rear	1	\$ 582.60	?
air intercooler	1	\$ S 1,358.20	X
washer tank	1	\$ S 159.10	X
brake master pump	1	\$ T 841.70	✓
brake servo unit	1	\$ D 1,256.90	✓
front corner panel	1	\$ B 193.90	✓
front bumper side retainer o/s	1	\$ CM 193.10	✓
air cleaner box	1	\$ M 637.40	✓

air intake air duct	1		\$	Ant	85.20	✓
front door harness wire	1		\$		1,587.90	?
fire wall wire harness to inner dashboard	1		\$		2,750.10	?
harness wire connector bar	1		\$	CM	84.60	✓
front outer pillar o/s	1		\$	Bu	377.10	✓
front inner pillar o/s	1		\$	Bu	360.60	✓
front step panel inner panel o/s	1		\$		422.80	?
front step panel top garnish o/s	1		\$		152.70	?
wheel arch panel o/s	1		\$	Bu	260.30	✓
wheel arch panel top garnish o/s	1		\$	Bu	275.30	✓
front pillar inner cover trim garnish o/s	1		\$		168.80	?
front pillar inner edge rubber o/s	1		\$		157.20	?
wheel arch panel edge rubber o/s	1		\$	Lu	61.40	✓
fuel accelerator pedal	1		\$		369.70	?
front door o/s	1		\$	Bu	1,794.10	✓
front door side mirror o/s	1		\$	Lu	1,015.80	✓
door outer top moulding o/s	1		\$	Bu	79.10	✓
door window glass o/s	1	Sharon	\$		432.60	✓
door glass channel rubber o/s	1		\$	Di	215.50	✓
door inner lock o/s	1		\$	Tu	492.10	✓
door lock striker o/s	1		\$	R	48.40	X
door channel o/s	1		\$		172.90	?
door hinge upper o/s	1		\$	B ₁	78.20	✓
door hinge lower o/s	1		\$	B ₂	78.20	✓
door weatherstrip o/s	1		\$	Lu	185.80	✓
door checker o/s	1		\$		138.60	?
door trim board o/s	1		\$	Bu	751.10	✓
door window regulator gear, motor o/s	1	Bill	\$		646.70	✓
door lower side speaker o/s	1		\$		282.20	?
door inner top moulding o/s	1		\$	Bu	85.30	✓
door window switch o/s	1		\$		138.80	?
door rear outer centre panel o/s	1		\$	B ₁	444.90	✓
door rear inner centre panel o/s	1		\$	R	322.70	X
door rear centre panel inner garnish o/s	1		\$		313.30	?
front door n/s	1		\$	Bu	1,794.10	✓
door window switch n/s	1		\$		138.80	?
dashboard	1		\$		774.40	?
glove box	1		\$		297.80	?
dashboard top side lower cover garnish	1		\$		221.60	?
dashboard lower centre garnish	1		\$		481.60	?
gear lever cover garnish	1		\$		289.30	?
meter top cover garnish	1		\$		323.40	?
air con ventilation casing assy	1		\$		3,070.10	?
air con blower casing	1		\$		1,025.30	?
dashboard lower cover garnish	1		\$		397.70	?
wiper motor, linkage	1		\$		895.70	?
brake pedal	1		\$		373.20	?
brake switch	1		\$		168.40	?
dashboard lower garnish o/s	1		\$		222.10	?
rear bumper	1		\$	Mg	373.10	✓
rear bumper side retainer	2		\$	Di	60.00	✓
rear tail lamp o/s	1		\$		256.90	?
front steel rim o/s	1		\$		454.70	?
front knuckle arm o/s	1		\$		451.70	?
front knuckle arm bearing o/s	1		\$		270.50	?
front lower arm o/s	1		\$		375.10	?
front lower arm ball joint o/s	1		\$		235.90	?
front upper arm o/s	1		\$		825.50	?
front tyre o/s	1		\$		320.00	?
rear inner wheel bearing	2		\$		238.80	?
rear outer wheel bearing	2		\$		378.60	?
			\$		48,767.90	
parts less 25%			\$		12,191.97	
			\$		36,575.93	

Miscellaneous

front windscreen glass sealant gum	\$	M	60.00	40.00
front windscreen glass inner seal	\$	M	40.00	30.00
front no. plate	\$	M	25.00	X
supply of clips	\$	M	60.00	—
supply of 8 liter radiator coolant	\$	M	60.00	25.00
towing of vehicle to workshop	(BII)	\$	130.00	7
supply of brake fluid	\$	M	25.00	—
repair of driver seat	\$		180.00	7
doors side marker sticker 2pc	\$	M	50.00	—

labour

to remove damaged windscreen and fixing of same	\$		120.00	✓
to cut, remove damaged panels, knocking, straightening, jacking of chassis member, door pillars and flattening of dented portion, welding of panels, fixing and align of parts of vehicle. Front and rear portion.	\$		2,800.00	2200
to remove of dashboard, meter, harness wire, air con ventilation casing, blower unit and air con system (heater and cooling coil casing unit) replace of parts, check and to recharge of air con gas etc	\$		600.00	2800
to remove turbo intercooler, intercooler pipes to facilitate replacement of radiator, fan clutch, fan blade, fan cowling and changing of air con liquid and suction hose. Fixing of same.	\$		280.00	1500
remove of front undercarriage, steering column and steering coupling box, air con pipes, facilitate repair on cutting, knocking, straightening flattening and welding of chassis side member. Change, replace of parts and fixing of same.	\$		400.00	2800
to wheel alignment after repair	\$		60.00	✓
to transfer of door lock, window gear regulator, gear motor, harness wire to new door.	\$		140.00	1200
to respray of front, rear and interior damaged affected portion	\$		2,100.00	1800
	\$		<u>43,705.93</u>	

Total Estimated Dollars: Forty Three Thousand Seven Hundred Five And Cent Ninety Three Only.

大進汽車噴漆廠
 Tai Cheng Motor Vehicle Spray Painting
 Blk 10 Ang Mo Kio Industrial Park 2A
 #01-03 Ang Mo Kio Auto Point
 Singapore 568047
 Tel: 6483 5515 Fax: 6483 5895

CONTACT MR CHUA . AT A/P 96265090

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/06/2020 10:56
Date Of Accident	24/06/2020 10:10
Exact Location Of Accident	ALONG ROAD 1 DAIRY FARM ROAD BT TIMAH EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH3943T
Insured/Policyholder	
Name Of Registered Owner	RH2SDECO CURTAINS
Co Reg No	5XXXX976W
Email Address	RH2SGENERAL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94238608
Alternative Phone No	OFFICE-83859367

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE VAN TURBO 5DR MT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2070064703

Cover Note Number

Driver

Name of Driver	AKKAS
NRIC No	GXXXX372K
Date Of Birth	28/06/1985
Occupation	INDOOR
Date Of Driving Pass	04/10/2017
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83859367
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 23 KIM KEAT LANE
Postcode 328878
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 1
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : CUNTAPAY EDWINDAQUIAOG
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED .

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: DRIVER DID NOT PROVIDE AT TIME OF REPORTING
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties TREE
Vehicle Category NA/UNKNOWN
Name of Driver
NRIC/Passport Number
Contact Number
Address

