

(Last Synchronised: 27 Jul 2020)

N/A NISSAN GKB45CLBHN 13.1 D (A) (Model not available in database)

Repairer's (Price-denominated Standard List)

Code: Goldbell Engineering Pte Ltd/XD6080Z/27/07/2020 16:10

ity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

urther Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CABIN ASSY <i>but</i> ✓	0.00	0.00	*34,617.00 F
2	1		*UD EMBLEM <i>rec</i> ✓	0.00	0.00	*50.50 F
3	1		*INSTRUMENT PANEL <i>(dashboard) de</i> ✓	0.00	0.00	*1,992.00 F
4	1		*HEADLINING TOP <i>de</i> ✓	0.00	0.00	*1,650.40 F
5	1		*TRIM, CAB RR END <i>de</i> ✓	0.00	0.00	*925.00 F
6	1		*RH MIRROR STAY ASSY <i>mis</i> ✓	0.00	0.00	*313.54 F
7	1		*RH MIRROR <i>mis</i> ✓	0.00	0.00	*150.00 F
8	1		*LH MIRROR STAY ASSY, MOTOR TYPE <i>dis</i> ✓	0.00	0.00	*550.00 F
9	1		*LH ROUND MIRROR <i>con</i> ✓	0.00	0.00	*125.60 F
10	1		*LH REAR VIEW MIRROR <i>scr</i> ✓	0.00	0.00	*150.00 F
11	1		*LH UNDER VIEW MIRROR <i>scr</i> ✓	0.00	0.00	*135.50 F
12	1		*RH FENDER ASSY <i>de</i> ✓	0.00	0.00	*780.00 F
13	2		*CABIN FRONT SHOCK ABSORBER <i>bt</i> ✓	0.00	0.00	*636.00 F
14	1		*CLUTCH/ BRAKE OIL RESERVOIR <i>? XAN</i>	0.00	0.00	*87.50 F X
15	1		*BRAKE OIL <i>? XAN</i>	0.00	0.00	*15.00 F X
16	1		*RH WIPER ARM WITH BLADE <i>bra</i> ✓	0.00	0.00	*110.00 F
17	1		*WIPER LINKAGE <i>? bt</i> ✓	0.00	0.00	*225.80 F
18	1		*COOLANT SURGE TANK <i>bt</i> ✓	0.00	0.00	*778.46 F
19	1		*COOLANT <i>rec</i> ✓	0.00	0.00	*48.90 F
20	1		*BRIDGE, CAB RR MOUNTING <i>? bt</i> ✓	0.00	0.00	*3,320.00 F
21	2		*CABIN REAR PNEUMATIC ABSORBER <i>rec</i> ✓	0.00	0.00	*1,665.80 F
22	1		*STEERING SHAFT <i>? bt</i> ✓	0.00	0.00	*1,760.00 F
23	1		*SENSOR ASSY, ACCELERATION PEDAL CONTROL <i>? bt</i> ✓	0.00	0.00	*1,420.00 F
24	1		*RH SIDE STEP LOWER GARNISH <i>con</i> ✓	0.00	0.00	*175.00 F
25	1		*RH SIDE STEP <i>X old damage</i>	0.00	0.00	*150.00 F X
Total Parts (S\$)						51,832.00

Goldbell Engineering Pte Ltd/XD6080Z/27/07/2020 16:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

on Miscellaneous Items

Particulars

Amount

ous Items

	COMPANY STICKER (FRONT PANEL) <i>new</i> ✓		75.00
	COMPANY STICKER (LH DOOR PANEL) <i>new</i> ✓		75.00
	COMPANY STICKER (LH REAR PILLAR) <i>new</i> ✓		75.00
1	COMPANY STICKER (RH DOOR PANEL) <i>new</i> ✓	305	75.00
1	COMPANY STICKER (ROOF TOP) <i>new</i> ✓		75.00
1	ERP BRACKET <i>new</i> ✓		20.00
7 1	UD SPEED LIMITER STICKER (WINDSCREEN) ? <i>Xnn</i>		89.50 <i>X</i>
Sub Total (S\$)			484.50

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	1750 3,800.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK. (PRE REPAIR CHECK AND POST REPAIR CHECK)	New	120 180.00
3	TO TRANSFER/REMOVE/INSTALL DOOR LOCK MECHANISM, CUSHION SEAT/GEAR LEVER/WIRING HARNESS	New	400 450.00
4	TO REFIX DASHBOARD	New	250.00
5	TO REMOVE & REFIX POWER STEERING TANK ASSY/COOLANT SPARE TANK/ BRAKE SYSTEM, TO CHECK FUNCTION	New	250 350 600.00
6	TO ADJUST ALIGNMENT	New	4785 75.00 ✓
7	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION	New	400 450.00
8	SUNDRIES	New	55.00 ✓
9	TO APPLY TUFF COAT	New	85.00
10	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC (WHOLE CAB)	New	1300 1,380.00
11	ROAD TEST FOR WORTHINESS AND SPEED LIMITER CUT OFF <i>Xnn</i>	New	60.00 <i>7.5 X</i>
Gross Labour Cost (S\$)			7,355.00

Goldbell Engineering Pte Ltd/XD6080Z/27/07/2020 16:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068



10 days

4/5

28/07/2020 @ 1530

Rey before after paint

EXCESS: 3K

REVERT

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 17 Sep 2020)**Parts:** N/A NISSAN GKB45CLBHNB 13.1 D (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Goldbell Engineering Pte Ltd/XD6080Z/17/09/2020 19:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*SHOCK ABSORBER ,CAB RR MOUNTING bt /	0.00	0.00	*651.40 F
2	1		*ROD CAB RR MOUNTING LATERAL bt /	0.00	0.00	*253.64 F
Total Parts (S\$)						905.04

F=Franchise part.

Goldbell Engineering Pte Ltd/XD6080Z/17/09/2020 19:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	IU UNIT nw ✓	155.80
Sub Total (S\$)			155.80

Estimates on Labour

There are no labour items selected.

Goldbell Engineering Pte Ltd/XD6080Z/17/09/2020 19:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

