



# 新福德車廠私人有限公司

## NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

27/07/2020

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

TP Chian  
Asher

Accident date: 26/07/2020

Estimated repair cost for vehicle no: GBH9742S TOYOTA HIACE TURBO 18'

CHASSIS: JTFHT02PX00245500

| S/n | Qty | Items / List                                   | U/price  | Amount                      |
|-----|-----|--|----------|-----------------------------|
| 1   | 1   | Rear Boot Lid <i>Distorted</i>                 |          | \$1,712.45 ✓                |
| 2   | 2   | Rear Boot Lid Hinge <i>xta</i>                 | \$171.70 | \$343.40 *                  |
| 3   | 1   | Rear Boot Lid Toyota Hiace Sticker <i>xta</i>  |          | \$57.60 ✓                   |
| 4   | 1   | Rear Boot Lid Emblem Logo <i>xta</i>           |          | \$41.10 ✓                   |
| 5   | 1   | Rear Boot Lid Centre Moulding <i>cluded</i>    |          | \$281.90 ✓                  |
| 6   | 1   | Rear Boot Lid Inner Lock <i>Damaged</i>        |          | \$374.25 ✓                  |
| 7   | 1   | Rear Boot Lid Inner Rubber <i>lit</i>          |          | \$381.90 ✓                  |
| 8   | 1   | Rear Boot Lid Inner Trim Board <i>Torn</i>     |          | <del>\$581.10</del> 16530 ✓ |
| 9   | 10  | Rear Boot Lid Inner Trim Board Clip <i>xta</i> | \$6.50   | <del>\$65.00</del> 30 ✓     |
| 10  | 1   | Rear Boot Lid Windscreen Seal <i>xta</i>       |          | \$105.00 ✓                  |
| 11  | 2   | Rear Tail Lamp <i>cluded</i>                   | \$374.45 | \$748.90 ✓                  |
| 12  | 2   | Rear Tail Lamp Panel <i>Repair</i>             | \$371.85 | \$743.70 *                  |
| 13  | 2   | Rear Tail Lamp Lower Cover <i>Repair</i>       | \$182.10 | \$364.20 *                  |
| 14  | 2   | Rear Tail Lamp Lower Cover Retainer <i>xta</i> | \$171.45 | \$342.90 *                  |
| 15  | 1   | Rear Bumper <i>Dented</i>                      |          | \$374.45 ✓                  |
| 16  | 8   | Rear Bumper Clip <i>xta</i>                    | \$6.50   | <del>\$52.00</del> 30 ✓     |
| 17  | 2   | Rear Bumper Side Retainer <i>xta</i>           | \$131.35 | \$262.70 ✓                  |
| 18  | 1   | Rear End Panel Outer <i>Dented</i>             |          | \$581.10 ✓                  |
| 19  | 1   | Rear End Panel Inner <i>Dented</i>             |          | \$591.25 ✓                  |
| 20  | 8   | Rear End Panel Top Clip <i>xta</i>             | \$6.50   | \$52.00 *                   |
| 21  | 1   | Rear Floor Panel <i>Repair</i>                 |          | \$1,972.45 ✓                |
| 22  | 1   | Rear Floor Panel Top Moulding <i>Best</i>      |          | \$274.45 ✓                  |
| 23  | 8   | Rear Floor Panel Top Moulding Clip <i>xta</i>  | \$6.50   | <del>\$52.00</del> 20 ✓     |
| 24  | 1   | Rear Spare Tyre Bracket <i>Best</i>            |          | \$172.10 ✓                  |
| 25  | 1   | Rear Exhaust <i>Best</i>                       |          | <del>\$1,712.85</del> 725 ✓ |
| 26  | 1   | Rear Centre Exhaust <i>xta</i>                 |          | \$1,829.10 *                |
| 27  | 1   | Rear Boot Lid Windscreen <i>Cut</i>            |          | \$974.50 ✓                  |

28 1 Rear Boot Lid Windscreen Seal *new* \$105.00 ✓

800895

600671

Subtotal :- \$15,149.35

| S/n | Qty | Items / Special Nett                      | U/price | Amount                 |
|-----|-----|---|---------|------------------------|
| 29  | 1   | Rear Boot Lid 70km/H Sticker <i>new</i>   |         | \$20.00 ✓ 10           |
| 30  | 1   | Rear Boot Lid Number Plate <i>new</i>     |         | \$50.00 X              |
| 31  | 1   | Rear Boot Lid Camera <i>new</i>           |         | \$680.00 X             |
| 32  | 1   | Rear Bumper Reverse Sensor <i>Damaged</i> |         | <del>\$350.00</del> 2w |
| 33  | 1   | Rear Floor Panel Plywood <i>2 New</i>     |         | \$650.00 X             |
| 34  | 1   | Rear Floor Panel Carpet <i>1 New</i>      |         | \$850.00 X             |

210

Subtotal :- \$2,600.00

**Labour charges**

To remove & refit cushion, plywood & carpet ~~\$380.00~~ 60.

To remove & refit reverse sensor and rear camera. ~~\$100.00~~ 80

To remove & refit rear windscreen ~~\$120.00~~ ✓

Gum \$50.00 ✓

To remove & refit rear & centre exhaust ~~\$380.00~~ 80

To check wiring ~~\$100.00~~ 30

Tuff kote ~~\$150.00~~ 80

Panel beating ~~\$1,800.00~~ 90

Spray painting ~~\$1,600.00~~ 90.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:.

2300

Subtotal :- \$4,680.00

Total:- \$22,429.35

68K

078

whl. 851671

L/S 68K

07 Days