

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 27/7/2020
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLL1545H
Chassis No: JM6BM42A8H0140817
MAKE / MODEL : Mazda 3 Sedan 1.5 AT
DATE OF ACCIDENT : 26/07/2020
YOUR INSURED VEHICLE NUMBER : SJF838A
MILEAGE : 218176 km

PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 F/L fender / CRU	1PC	\$ 350.60	\$ 350.60
2 F/L fender inner liner / CRU	1PC	\$ 150.90	\$ 150.90
3 F/L headlamp / CRU	1PC	\$ 1,100.00	\$ 1,100.00
4 Front bumper / BP	1PC	\$ 971.40	\$ 971.40
5 F/L signal lamp cover / SR	1PC	\$ 180.00	\$ 180.00
6 F/L signal lamp assy / CRU	1PC	\$ 350.00	\$ 350.00
7 Radaitor grille LH moulding / SCR	1PC	\$ 220.00	\$ 220.00
LH Refinish / BR \$60			\$ 2,572.90
20% DISCOUNT SS:			\$ 514.58
			\$ 2,058.32
S/Nett			
Bumper clips / NEC	1 Set	\$ 100.00	

LABOUR CHARGES

1 To labour charge for removing out front support panel/ F/L fender and front bumper rout to facilitate repairs and replacement of damaged parts	\$ 900.00
2 To respray F/L fender, front bumper, front bonnet	\$ 1,200.00
LABOUR TOTAL S\$:	\$ 2,100.00
TOTAL S\$:	\$ 4,158.32
7% GST	\$ 291.08
GRAND TOTAL S\$:	\$ 4,449.40

Repair days.
4 days
L/S.
After paint.
Sun Pn (LKS)
28/07/2020
TP without prejudice.

L/S
\$3,000
4 days

2,628.72
1,130
3,758.72
- 20%
3,006.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: