

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/1C/EA/0217/20  
DATE : 27-JUL-2020

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
S(079909)  
TEL : 63896111  
FAX : 62247175

OWNER'S NAME : MR RAJKUMAR S/O GHANA SEGARAN  
ADDRESS : APT BLK 458 ANG MO KIO AVENUE 10  
#20-1586  
S(560458)  
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : 10943549  
VEHICLE NO : SJX1690G  
MODEL CODE : FRLARBZJ11UEA--A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRA2244293A-J11WB/BC  
CHASSIS NO : SJNFEAJ11U1599494  
MILEAGE : 57800 KM  
DATE IN : 27/07/2020  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : ELMER  
ACCIDENT DATE : 26/07/2020

- 9645 0084 elmr@fanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJX1690G  
-----

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR REAR END PANEL, RENEW REAR BUMPER <i>390 x 2</i>	1170.00	<i>399 780</i>
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME <i>259 x 2</i>	700.00	<i>250 500</i>
3 ZZ/003	REMOVE AND INSTALL BOTH REAR COMBINATION LAMP TO FACILITATE REAR BUMPER REPLACEMENT	48.00	/
4 ZZ/004	RENEW REVERSE SENSOR	110.00	/
TOTAL LABOUR CHARGES		2028.00	

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJX1690G

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 RH STAY RR BUMPER ? / BT	H5210-4EAMA	141.00	/	
2 LH STAY REAR BUMPER ? X NM	H5211-4EAMA	141.00	X	
3 REINFORCEMENT REAR BUMPER ? / BT	H5030-4EAMA	691.50	/	
4 ENERGY ABSORBER RR BUMPER ? X NM	85090-4EAOB	141.40	X	
5 LH SIDE BRACKET RETAINER REAR BUMPER ? X NM	85221-4EAOA	38.90	X	
6 RH SIDE BRACKET RETAINER RR BUMPER ? X NM	85220-4EAOA	38.90	X	
7 CLIP RR BUMPER @ SGD \$ 1.30 EACH / KC	01553-05933	7.80	/	
8 TOW HOOK COVER REAR BUMPER / CHT	85071-4EAOA	18.80	/	
9 REAR BUMPER / DD	85022-4EAOH	796.70	/	
10 SUNDRIES / m	NPN			50.00 20
11 SENSOR-REVERSE / SM	SENSOR			250.00 /
SUB TOTAL		2016.00	0.00	300.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		403.20	0.00	0.00
GRAND TOTAL		1612.80	0.00	300.00
OVERALL TOTAL		1912.80		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJX1690G

TOTAL LABOUR CHARGES	2028.00
TOTAL SPARE PARTS CHARGES	1912.80
GRAND TOTAL	3940.80 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :  
SURVEYED DATE :  
AUTHORIZED DATE :  
EXCESS CLAUSE : 0.00  
LIABILITY : 0.00  
REMARKS :

Steve CLKK)

30/7/79, 10.00 am

WH A-L  
P/P

3 days

Ry Bel spy

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: