



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC19008335/R1tf3e2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 11-08-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7253L	Veh. Inspected	SLM 1451P
Policy No.	Z/19/VC05/001617-001	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/021781	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	28/07/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE 1.5A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81100405	Colour	GREY
Odometer	200361	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	GITI	6 mm
L/H Front Tyre	185/60 R15	GITI	6 mm
R/H Rear Tyre	185/60 R15	GITI	6 mm
L/H Rear Tyre	185/60 R15	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/05/2019	Inspection Date	10/05/2019
Survey held at	KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------