



ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 539266

GST Reg No.: 53192889J

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

(3rd Party Claim Against AIG Incurred sum \$40560)

POA: 27.07.2020

Repair Estimate

Vehicle No. : SMAA079M
Make & Model : VOXY hybrid 1.8 x CVT

Submitted by : Ben
COE Expiry : 05.06.2028

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01	RH fender / bnc	01	\$729.00	630	
02	Front bumper X Repair	01	\$1719.00	X	
03	Hybrid logo / nbc	01	\$65.00	47.9	
				677.9	
			-25%	508.43	
	Special net				
01	Clips & retainers studs \$50 / pcf / nbc	01	\$50.00	30	
	Labour Description				
01	Dismantle / Assembly of fender / bumper panel knocking on support panel	01	\$800.00	400	
				300	
01	Spray painting of all parts affected including polish & wash	01	\$800.00	500	
				1338.43	
	3 x 2 days				
	part by part				
	before paint photos				
	Ben Qiang - 82880282				
	29/7/2020				

Note: If any the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: