

POH HOCK MOTOR TRADING CO

7A Ontario Ave #03-08, Singapore 576197

Tel: 96696997 Fax: 64594569

Email: boonhockang@hotmail.com

GST No: MX-0468931-E

Not Authorised

11 Sep @

Repair After Rain

27.07.2020

KWEK ZHENG NING

4J Marigold Drive

Singapore 576349

ESTIMATE COST OF REPAIR TO M/CAR SDW222H BMW 325 COUPE

SUPPLY OF PARTS:

1. 1 PC rear bumper	<i>dispt B1</i> 1,250.15	✓
2. 2 pc rear bumper side retainer @\$50.20 x 2	100.40	✓
3. 2 pc rear bumper bracket @\$50.20 x 2	100.40	?
4. 1 pc rear bumper beam	460.85	?
5. 1 pc rear bumper towing cover	<i>mi</i> 39.15	✓
6. 4 pc rear bumper sensor @\$238.05 x 4	<i>nc</i> 952.20	✓
7. 1 pc rear tail lamp	<i>cm</i> 413.00	✓
8. 1 pc rear tail lamp lower garnish	55.00	?
9. 1 pc rear boot lid reflector	<i>su</i> 289.10	X

3,660.25

183.01

Less 5%

3,477.24

600.00 *2801*

LABOUR CHARGE & MISC

To dismantle & replace rear bumper, reverse sensors,
Bumper beam, brackets, retainers, garnish, tail lamps,
Reflector & reshape /align rear bumper.

600.00 *4001*

PAINTING:

To putty and spray painting on rear bumper cover and
accident affected area.

4,677.24

327.40

GST 7%

Total :

S \$ 5,004.64

=====

