

POH HOCK MOTOR TRADING CO

7A Ontario Ave #03-08, Singapore 576197

Tel: 96696997 Fax: 64594569

Email: boonhockang@hotmail.com

GST No: MX-0468931-E

27.07.2020

KWEK ZHENG NING

4J Marigold Drive

Singapore 576349

Not Notified

11 Sep 8

Repair After Pain

3 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE COST OF REPAIR TO M/CAR SDW222H BMW 325 COUPE

SUPPLY OF PARTS:

1. 1 PC rear bumper	dis 1,250.15	✓
2. 2 pc rear bumper side retainer @\$50.20 x 2	100.40	✓
3. 2 pc rear bumper bracket @\$50.20 x 2	100.40	✓ 1PC O/S DAM
4. 1 pc rear bumper beam	460.85	✓ DAM
5. 1 pc rear bumper towing cover	mi 39.15	✓
6. 4 pc rear bumper sensor @\$238.05 x 4	nc 952.20	✓
7. 1 pc rear tail lamp	cm 413.00	✓
8. 1 pc rear tail lamp lower garnish	55.00	✓ DAM
9. 1 pc rear boot lid reflector	su 289.10	X

3,660.25

183.01

Less 5%

3,477.24

600.00 2801

LABOUR CHARGE & MISC

To dismantle & replace rear bumper, reverse sensors, Bumper beam, brackets, retainers, garnish, tail lamps, Reflector & reshape /align rear bumper.

600.00 4001

PAINTING:

To putty and spray painting on rear bumper cover and accident affected area.

4,677.24

327.40

GST 7%

Total :

S \$ 5,004.64

=====

