

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
LONPAC INSURANCE BHD			Ref : CS3/LPC20007160/Qtf3e2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date: 17-08-2020 Code: LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM					
Insi	ured Veh.	SKG 2827B	Veh. Inspected	SJN 2504H	
Pol	icy No.	Z/19/VP05/023584-001	Coverage (\$)	0.00	
Cla	im No.	19/20/20/VP05/023455	Excess (\$)	0.00	
Ass	ign From	GERALD POH WEE BIN	Assign Date	27/07/2020	
2. Vehicle Particulars & Condition					
Mal	ke & Model	TOYOTA COROLLA ALTIS	c.c	1598	
Eng	jine No.	HIDDEN	Year of Reg.	2009	
Cha	assis No.	MR053ZEE106127760	Colour	BEIGE	
Odd	ometer	169047	Steering	IN ORDER	
Bra	kes	IN ORDER	Modification	SPORTS RIM	
Ger	neral	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
-	Front Tyre	205/55 R16	YOKOHAMA	6 mm	
_	Front Tyre	205/55 R16	YOKOHAMA	6 mm	
_	Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
	Rear Tyre	205/55 R16	<u> ҮОКОНАМА</u>	6 mm	
4. Description of Damages					
THE	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5. General Information					
_	ident Date	09/07/2020	Inspection Date	13/07/2020	
Sur	Survey held at INFINITY CAPITAL & INSURANCE				
_	38 WOODLAND CLOSE #01-08 MEGA @ WOODLAND SINGAPORE 737856				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
EST	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				