

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 8660Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT DOOR LH (N)	DENTED	1,354.80	1,254.00
1	FRT DOOR PROTECTOR LH (N)	сит	187.40	187.40
1	FRT DOOR OUTER MOULDING LH (N)	NOT NECESSARY	199.10	-
1	FRT DOOR RUBBER LH (N)	NOT NECESSARY	156.20	-
1	FRT DOOR INNER LOWER RUBBER LH (N)	NOT NECESSARY	88.90	-
1	REAR DOOR LH (N)	DENTED	1,258.90	1,258.90
1	REAR DOOR PROTECTOR LH (N)	СИТ	156.70	156.70
1	REAR DOOR OUTER CHROME MOULDING LH (N)	NOT NECESSARY	177.90	-
1	REAR DOOR RUBBER LH (N)	NOT NECESSARY	144.60	-
1	REAR DOOR INNER LOWER RUBBER LH (N)	NOT NECESSARY	78.10	-
1	REAR BUMPER (N)	NOT NECESSARY	840.00	-
1	REAR BUMPER RETAINER LH (N)	NOT NECESSARY	79.60	-
1	REAR BUMPER CHROME LH (N)	NOT NECESSARY	166.20	-
1	REAR BUMPER MUDFLAP LH (N)	NOT NECESSARY	99.70	-
	LESS 10% DISCOUNT		-498.81	-285.70
			4,489.29	2,571.30
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
			60.00	-
	LABOUR			
	TO CHECK WIRING .		50.00	30.00
	TO REMOVE AND REFIX FRT DOOR GLASS.		100.00	40.00
	TO REMOVE AND REFIX REAR DOOR GLASS .		100.00	40.00
	TO REMOVE AND REFIT DOOR TRIM .		100.00	80.00
	TO SPRAY PAINTING .		1,200.00	600.00
	TO SPRAY UNDERSEAL.		120.00	50.00
	TO REMOVE AND REPLACE THE DAMAGED		1,000.00	600.00
	PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS.			
	SKITCHO , AND I CK COTTINO, WEEDING WORKS.		2,670.00	1,440.00

Report Ref No. CS/AGI20007802/Atf3q2



Page No.:2 of 2

GRAND TOTAL	7,219.29	4,011.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		3,200.00

Report Ref No. CS/AGI20007802/Atf3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.