

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD

190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199

FAX: 6725 0853

ATTN: Motor Claim Department

Estimate No: EST2000145

Date: 28 Jul 2020

Veh Reg No: SJS8660Z

Make/Model: NISSAN TEANA 2.0L
CVT ABS D/AIRBAG
2WD

Chasis No: JN1BDUJ32Z0001055

Reg. Date: 11/09/2009

Your Ref No: SLB2395U

Claim Type: Third Party

Accident Date: 27/07/2020

TP Veh Reg No: SLB2395U

Estimate Repair Cost to Vehicle No :SJS8660Z

Quantity	Description	List Price	Amount
		SS	SS
Net Price			
1	1 PC FRT DOOR LH <i>Dented</i>	1,354.80 ✓	1254
2	1 PC FRT DOOR PROTECTOR LH <i>cut</i>	187.40 ✓	
3	1 PC FRT DOOR OUTER MOULDING LH <i>new</i>	199.10 +	
4	1 PC FRT DOOR RUBBER LH <i>new</i>	156.20 +	
5	1 PC FRT DOOR INNER LOWER RUBBER LH <i>new new</i>	88.90 +	
6	1 PC REAR DOOR LH <i>Dented</i>	1,258.90 ✓	1255
7	1 PC REAR DOOR PROTECTOR LH <i>cut</i>	156.70 ✓	
8	1 PC REAR DOOR OUTER CHROME MOULDING LH <i>new</i>	177.90 +	
9	1 PC REAR DOOR RUBBER LH <i>new</i>	144.60 +	
10	1 PC REAR DOOR INNER LOWER RUBBER LH <i>new</i>	78.10 +	
11	1 PC REAR BUMPER <i>new</i>	840.00 +	
12	1 PC REAR BUMPER RETAINER LH <i>2</i>	79.60 +	
13	1 PC REAR BUMPER CHROME LH <i>new</i>	166.20 +	
14	1 PC REAR BUMPER MUDFLAP LH <i>new</i>	99.70 +	
		4,988.10	
		Less 10%	
		498.81	4,489.29
Special Net			
15	1 SET REAR BUMPER CLIPS <i>new</i>	60.00 +	
		60.00	60.00
Labour			
16	1 TO CHECK WIRING <i>fitting</i>	50.00 <i>30</i>	
17	1 TO REMOVE AND REFIX FRT DOOR GLASS <i>fitting Glass</i>	100.00 <i>40</i>	
18	1 TO REMOVE AND REFIX REAR DOOR GLASS <i>fitting Glass</i>	100.00 <i>40</i>	
19	1 TO REMOVE AND REFIT DOOR TRIM <i>fitting</i>	100.00 <i>80</i>	
20	1 TO SPRAY PAINTING	1,200.00 <i>600</i>	
21	1 TO SPRAY UNDERSEAL	120.00 <i>50</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Estimate No: EST2000145

Date: 28 Jul 2020

Veh Reg No: SJS8660Z
Make/Model: NISSAN TEANA 2.0L
CVT ABS D/AIRBAG
2WD

Chasis No: JN1BDUJ32Z0001055

Reg. Date: 11/09/2009

Your Ref No: SLB2395U

Claim Type: Third Party

Accident Date: 27/07/2020

TP Veh Reg No: SLB2395U

Estimate Repair Cost to Vehicle No :SJS8660Z

Quantity	Description	List Price	Amount
		SS	SS
22	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	600
	1440	2,670.00	2,670.00
Total			S\$ 7,219.29
Add GST @ 7%			505.35
Total Amount Payable			<u>S\$ 7,724.64</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED TWENTY FOUR AND CENTS SIXTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]

Adrian Lj
1/s 07/08/20

05 Days.

total 4011.30
1/s: 32K

32K